



Draft Preliminary Geotechnical Engineering Report Piscataway Drive Slope Failure

**Fort Washington, Prince George's County,
Maryland**



Prepared For

Prince George's County Government, Maryland

**THIS DRAFT REPORT WAS PREPARED FOR THE EXPRESS
PURPOSES OF PROVIDING ADVICE AND TECHNICAL
EXPERTISE TO THE COUNTY EXECUTIVE STAFF TO ASSIST IN
THEIR DECISIONAL PROCESSES**

Prepared By

KCI Technologies, Inc.

May 19, 2014



ENGINEERS • PLANNERS • SCIENTISTS • CONSTRUCTION MANAGERS

936 RIDGE BROOK ROAD • HUNT VALLEY, MD 21152 • 410-316-7800 • (FAX) 410-316-7817 • WWW.KCI.COM

Phone (410) 316-7800
FAX (410) 316-7935
Direct Dial (410) 316-7919

May 19, 2014

Nicholas A. Majett
Acting Chief Administrative Officer
Prince George's County Government
County Executive's Office
14741 Governor Oden Bowie Drive
Upper Marlboro, Maryland 20772
namajett@co.pg.md.us

Subject: Draft Preliminary Geotechnical Engineering Report
Piscataway Drive Slope Failure
Fort Washington, MD, Prince George's County, Maryland
KCI Job. No.: 07100627.W

**THIS DRAFT REPORT WAS PREPARED FOR THE EXPRESS PURPOSES OF
PROVIDING ADVICE AND TECHNICAL EXPERTISE TO THE COUNTY
EXECUTIVE STAFF TO ASSIST IN THEIR DECISIONAL PROCESSES**

Dear Mr. Majett:

KCI Technologies, Inc. (KCI) has completed the preliminary geotechnical exploration for the Piscataway Drive slope failure.

The attached report presents a description of the existing site, subsurface conditions encountered, and recommendations for stabilizing the failed slope.

We appreciate the opportunity to provide these services and look forward to serving as your geotechnical consultant throughout this project. Please contact us if you have any questions regarding the information presented.

Sincerely,

KCI TECHNOLOGIES, INC.

Shanzhi Shu, PhD, PE
Senior Geotechnical Engineer

Kwabena Ofori-Awuah, PE, ENV-SP
Practice Leader, Geotechnical Engineering

Kofi Acheampong, PhD PE, ENV-SP
Chief Geotechnical Engineer

"PROFESSIONAL CERTIFICATION: I HEREBY CERTIFY THAT
THESE DOCUMENTS WERE PREPARED OR APPROVED BY ME,
AND THAT I AM A DULY LICENSED PROFESSIONAL ENGINEER
UNDER THE LAWS OF THE STATE OF MARYLAND, LICENSE
NO.: 25981 EXPIRATION DATE: 3/22/15"




TABLE OF CONTENTS

1.0 INTRODUCTION.....	1
1.1 PROJECT INFORMATION	1
1.2 SCOPE OF SERVICES.....	1
2.0 EXISTING SITE AND SUBSURFACE CONDITIONS.....	3
2.1 EXISTING SITE CONDITIONS	3
2.2 GEOLOGIC SETTING	4
2.3 SUBSURFACE EXPLORATIONS AND IN-SITU TESTING.....	5
2.3.1 Standard Penetration Test.....	6
2.3.2 Cone Penetration Test.....	6
2.3.3 Undisturbed Soil Sampling.....	7
2.3.4 Soil Conditions.....	8
2.3.5 Groundwater and Cave-in Conditions	9
2.4 SLOPE MOVEMENT MONITORING	11
2.5 LABORATORY TESTING	12
3.0 GEOTECHNICAL EVALUATIONS	14
3.1 SLOPE STABILITY ANALYSES	14
3.2 POTENTIAL CAUSES OF THE EXISTING LANDSLIDE	16
4.0 GEOTECHNICAL RECOMMENDATIONS.....	18
4.1 GENERAL	18
4.2 SLOPE STABILIZATION OPTIONS	18
4.3 UTILITY COORDINATION AND RECONSTRUCTION RECOMMENDATIONS.....	20
4.4 ENVIRONMENTAL COORDINATION	21
4.5 ROADWAY RECONSTRUCTION AFTER THE SLOPE STABILIZATION PROCESS HAS BEEN COMPLETED.....	22
5.0 STRATEGY FOR MOVING FORWARD.....	24
6.0 BASIS OF RECOMMENDATIONS.....	25

APPENDICES

APPENDIX A

Figure 1: Site Location Map
Figure 2: Exploration Plan
Figure 3A – Regional Geology Map
Figure 3B – Site Geology Map
Figure 4A: Subsurface Profile A – A'
Figure 4B: Subsurface Profile B – B'
Figure 4C: Subsurface Profile C – C'
Figure 5: Potential Failure Plane in Boring B-15 (22'-24')

APPENDIX B

Test Boring Logs
Cone Penetrometer Testing Results
Field Exploratory & Slope Monitoring Procedures

APPENDIX C

Laboratory Test Results
Soil Data Summaries
Laboratory Testing Procedures

APPENDIX D

Slope Stability Analyses (Back Calculations)
Slope Stabilization Options

APPENDIX E

Slide Features

APPENDIX F

Roadway Plans

EXECUTIVE SUMMARY

This report contains the results of our subsurface explorations and preliminary geotechnical evaluations for repairing the approximately 1,500-foot section of failing slopes and ground movements along Piscataway Drive, Fort Washington, Prince George's County, Maryland. We performed 15 soil test borings, 10 cone penetration tests; and installed one piezometer to explore the subsurface conditions at the site. Additionally, we installed six inclinometers to monitor ground movements.

The test borings and CPT data revealed a soil profile consisting of three distinct strata within their termination depths, consistent with published geology. Stratum I (Ta, Nangemoy Formation) generally consisted of moist, brown, light brown, dark gray, very loose to medium dense Silty Sand, Clayey Sand, Sand with Gravels, and interbedded with soft to stiff Sandy Silt and Sandy Clay layers. A 20 to 30-ft thick layer of Stratum II (Marlboro Clay, Tm) underlies Stratum Ta. It consisted of moist to wet, reddish brown, brown, light gray to gray, Lean Clay with occasional thin lenses of micaceous Silt. Locally, we encountered Fat Clays within this stratum. Beneath the Tm, we encountered Stratum III (Aquia Formation, Ta) which consisted of moist to wet, olive gray, greenish gray to dark gray, Silty Sand and Sandy Silt with mica and calcareous shell fragments scattered throughout the stratum.

Based on preliminary site evaluations, analyses and review of historic information, the existing Marlboro Clay stratum made the site susceptible to slope failures. The intense and rapid infiltration of rainfall that occurred prior to the slope failure created saturated soil conditions resulting in significant loss of shear strength. The exploration data provided evidence of a failure plane within the Marlboro Clay stratum.

KCI proposes three options to stabilize the slopes with each soil-structure system extending beyond the anticipated failure planes. They are: 1) Drilled Shaft foundation along the east and west slopes abutting the roadway and Micropile Anchors at the head scarp upslope; 2) Drilled Shaft Foundation for east slope and Micropiles for west slope; 3) Micropiles for both east and west slopes. We anticipate that the resulting ground movements indicated by the inclinometer readings will have significant implications for the slope rehabilitation options. We therefore recommend that additional detailed analyses and design, constructability evaluation and cost analyses be performed for each option as part of the design purposes.

Design and construction considerations should not be based solely on the executive summary without reading the entire report.



1.0 INTRODUCTION

1.1 PROJECT INFORMATION

The project is located in Prince George's County in the proximity of 13700 to 13816 Piscataway Drive, Fort Washington, Prince George's County, Maryland. The site is bordered by Piscataway Creek on the east and Pine Road to the west. The Piscataway Drive, which traverses the site, is bordered by steep slopes on both sides with homes perched above and below the roadway. Figure 1 illustrates the site.

Historically, the slopes above and below Piscataway Drive have been experiencing surficial movement over a long period of time, but on May 4, 2014, significant failure.

Cracks began appearing in the pavements on Piscataway Drive on May 2, 2014 and escalated into major slope failures and pavement distress on May 4, 2014. Prior to May 2, there were no visible cracks or fractures on the slopes. Cracks, however, appeared on the slopes and widened on May 4 resulting in continuous fracture and downward movement of the western slope for a distance of approximately 450 feet long. The depth of failure along the slopes ranged from about 4 feet to about 20 feet. The deeper failure depths were results of root bulbs from several toppled trees during the slope failure.

The slope failure has directly threatened six homes, disrupted power, water supply, communications and other services to an additional 22 homes along the Piscataway Drive. It has also jeopardized the use of most of roadway from 13700 Piscataway Drive to the southernmost part of the drive. The affected portion of Piscataway Drive remains closed and the County has determined and declared numerous homes in the vicinity of the slide unfit and/or unsafe for occupancy.

1.2 SCOPE OF SERVICES

The purpose of this study is to obtain specific subsurface data at the site, review existing site geologic data and assess the cause of the slope failure and develop recommendations for:

- Rehabilitating the slope failure;
- Reconstructing Piscataway Drive;
- Repairing the utilities; and
- Options for moving forward in the design and construction phases.

Assessments of site environmental conditions or the presence or absence of pollutants in the soil, rock, surface water, or groundwater of the site were beyond the proposed objectives of our studies.

The report for this study includes the following:

- A brief review of our field and laboratory test procedures and their results
- Evaluation of subsurface conditions to include:
 - Review of surface topographic features and site conditions
 - Review of site geologic conditions
 - Review of near surface soil conditions
 - Estimates of subsurface profiles, as necessary, to illustrate subsurface conditions
- A review of possible causes of slope failure
- Evaluation of various alternatives for stabilizing the slopes
- Recommendations for stabilizing the slopes, reconstructing the affected portions of the Piscataway Drive, repairing the damaged utilities, and
- Options for moving forward in the design and construction phases



2.0 EXISTING SITE AND SUBSURFACE CONDITIONS

2.1 EXISTING SITE CONDITIONS

KCI conducted a site reconnaissance on May 3rd and 4th, 2014. The purpose of the site reconnaissance was to observe and document existing surface conditions. Information gathered during the site visit and site GIS data provided to us by Messieurs Unmesh Patel and Dwight Joseph of Prince George's County were used to help us interpret the subsurface data and to detect conditions that could affect our evaluations and recommendations.

The site topography is generally hilly. Piscataway Drive traverses the site. The difference in elevations between the top of the hill and the Piscataway Drive is approximately 65 feet. The elevation difference between the highest and lowest point of the site is approximately 100 feet. There are several residential buildings east and west of the Piscataway Drive. The slopes west of the roadway are about 1.5 Horizontal to one Vertical (1H:1V) or steeper downwards towards the Piscataway Drive. The eastern slopes are generally 1.5H: 1V to 3H: 1V or gentler towards the Piscataway Creek. The slopes are generally covered with thick brush and large trees.

Soils when exposed appeared soft, moist and generally silty sands with organics. We did not observe any rock outcrops. Though it had rained the previous night, there was no evidence of surficial or ponded water except areas where underground water force main had cracked. Prior to the visit, the area had experienced high levels of precipitation over a short period of time.

We observed evidence of slope failure on both sides of the roadway. Additionally there were several cracks openings on the order of three to six inches in width in the pavement structure. The pavement edges had also settled several inches with the highest settlement of about four feet occurring around 13700 Piscataway Drive. The soil mass near the top of the hill had moved laterally downslope towards the roadway about two to three feet, and on the average, had settled approximately eight feet. Vertical cracks were visible due to this movement. Several trees had toppled, as a result of the slope failure, and had snapped the overhead utility lines. We observed evidence of past slope movement which appears to be



surficial movement of the soil mass. At a nearby previously condemned two-story structure located at 13710 Piscataway Drive we observed evidence of lateral movement and settlement cracks. There were several fissures in the driveway and around the house. We observed several distresses in the foundation wall. We further observed that the driveway leading to the garages is no longer accessible due to ground movement.

Residents recall minor sloughing of the slopes which are consistent with our observations during the site reconnaissance. We, however, did not observe any evidence of past slope repairs nor were we provided any records indicating that. We did not observe any storm drainage system in the vicinity of the failed slopes.

Underground utilities consist of water and sewer mains with service power and other lines to the various premises within the site. There are overhead utility which consist of power, communications and cables lines.

2.2 GEOLOGIC SETTING

Based on a review of the Geologic Map of Prince George's County (2003), the site is underlain by unconsolidated sediments ranging in geologic times from Holocene to Lower Paleocene. It is dominated by relatively thick, tripartite Paleocene-Eocene section- the Aquia (Ta) and Nanjemoy (Tn) Formations separated by the 20 to 30 feet of Marlboro Clay (Tm) (Figures 3A & 3B, Appendix A). These three units have an aggregate thickness of about 300 feet in outcrop. Both the Aquia and Nanjemoy are variably muddy, fossiliferous greensands in contrast to the Marlboro which is a thin but persistent pinkish to gray plastic clay. The Paleocene-Eocene section includes about 500 ft. of sediment.

The Aquia is composed of sand, fine-to medium-grained, poorly sorted well sorted, containing as much as 40 percent glauconite. Thin layers of calcareous shelly sandstone are scattered through the unit giving it the "salt and pepper" speckled. It is generally greenish gray to medium gray in color.

The Nanjemoy consists of mostly quartz sand, fine-to coarse-grained, with a variable amount of interstitial silt-clay and as much as 50 percent of green glauconite, also imparting a “salt and pepper” aspect to the sediments. Poorer outcrops are found along the Piscataway Creek. The glauconite sand in this formation is medium-gray to dark greenish gray, where unweathered. The silty-clay is dark-gray to chocolate-brown in color.

The Marlboro Clay is a continuous stratum throughout Southern Maryland. It is poorly exposed, mostly because it is thin and covered by slumping of the overlying sediments. In the valleys of the Piscataway and Mattawoman Creeks, the clay is effectively buried Holocene alluvium. Scattered patches of typically brownish red Marlboro clays are exposed along MD 210 just north of Piscataway Creek in Prince Georges County. The Marlboro Clay is a thin but highly distinctive unit composed of dense, brittle clay, ranging from thickly-bedded to finely laminated, lenticular or hummocky in part, containing partings and thin lenses of micaceous and lignitic laminated silt. It is usually pale-red to silvery-gray, and contains minor interbedded silt which is yellowish gray to pale-gray in color.

2.3 SUBSURFACE EXPLORATIONS AND IN-SITU TESTING

KCI's sub-contractors, CenKen Group, LLC (CenKen) and Hillis-Carnes Engineering Associates, Inc. (HCEA) performed emergency subsurface explorations in the areas of the failing slope. The exploration program consisted of 15 standard penetration test (SPT) borings and 10 cone penetrometer test (CPT) soundings. Additionally, we installed six inclinometers and one groundwater monitoring well (piezometer). We conducted the subsurface explorations from May 6 to May 15, 2014 in accordance to the procedures presented in Appendix B. The depth of the explorations ranged from 40 feet to 100 feet into natural soils. The approximate exploration boring and tests locations are shown on Figure 2 in Appendix A. The boring logs and CPT are included in Appendix B.

2.3.1 Standard Penetration Test

We drilled test borings in general accordance with ASTM D420 procedures presented in Appendix B. The borings were advanced using ATV drill rigs equipped with hollow stem augers (HSA) and mud-rotary drilling in cased holes in general accordance with ASTM D1452. We conducted continuous standard penetration tests (SPTs) in the borings in general accordance with ASTM D 1586.

We performed standard penetration tests (SPT) borings in accordance with ASTM D1586. The SPT method consisted of advancing a two-inch diameter sampling spoon to a depth of 18 inches by driving it with a 140-pound hammer falling 30 inches. The values reported on the boring logs are the blows required to advance three successive six-inch increments. The first six-inch increment is considered as seating. The sum of the number of blows for the second and third increments is the "N" value. The "N" value is used to infer the general indications relative density and compressibility of the soils. KCI obtained soil samples using the SPT method and sampling was performed at two and half-foot intervals to a depth of ten feet below existing ground surface (bgs) and every five feet thereafter to boring terminations depth. We obtained representative disturbed soil samples during these tests and used them to classify the soils encountered. We placed the recovered representative soil samples in six-inch glass jars and transported to the laboratory for testing.

KCI geotechnical engineers visually classified the recovered soil samples in general accordance with ASTM D 2488 Standard Practice for Description and Identification of Soils. We classified soil samples with respect to texture in accordance with the Unified Soil Classification System (USCS). Boring logs describing the subsurface soils and groundwater conditions encountered at each of the boring locations are presented in Appendix B. The existing ground surface elevations indicated on the logs are based on field survey information provided by KCI-Survey.

2.3.2 Cone Penetration Test

We performed cone penetration tests (CPT) soundings in general accordance with ASTM D5778 at ten locations within the general project area between May 9 and 13, 2014. We use the results of the soundings

to characterize the existing subsurface conditions within the unstable ground and slope areas. In addition, we performed localized pore pressure dissipation tests at test locations CPT-1 and CPT-5. The approximate test locations are shown on the attached Figure 2. We have provided summary tables soundings of the CPT results in Appendix B. We terminated the sounding depths at pushing refusals between 38 and 75 feet below existing ground surface, typically in excess of about 55 feet. We inferred soils in general accordance to Soil Behavior Types proposed by Robertson (1990).

We performed CPT tests in general accordance with ASTM D5778. CPT permits continuous explorations and profiling of the subsurface conditions while minimizing retrieval of subsurface materials. This exploration method employs sensors that are pushed into the ground to infer the properties of both soils and pore fluids. Known as direct-push technology, this method can map out the vertical and lateral extents of stratigraphic layers, as well as the distribution of groundwater conditions.

In combination with the test boring information, we will use the CPT results to identify loose/soft and disturbed soils strata and weak zones, and predict or confirm the existing failure planes at depth. Also, it will provide soil and groundwater data for characterizing the stress history and shear strength parameters of in-situ soil materials. By using standard engineering correlations, the geotechnical properties of stratigraphic layers can be inferred. Inferred properties include constrained modulus, undrained shear strength, residual shear strength, friction angle, overconsolidation ratio, and the coefficient of consolidation.

2.3.3 Undisturbed Soil Sampling

Split-barrel samples are suitable for visual examination and classification tests but are not sufficiently intact for quantitative laboratory tests requiring undisturbed samples. Therefore, we obtained relatively undisturbed samples in selected borings by drilling to the desired depth and hydraulically forcing a section of 3-inch O.D., 16 gauge steel tubing into the soil. The sampling procedure is described by ASTM D 1587. We carefully removed each tube, together with the encased soil, from the ground, made airtight and transported to the laboratory. The appropriate test boring records show depths of undisturbed samples.

2.3.4 Soil Conditions

Figures 4A, 4B, and 4C in Appendix A depict generalized subsurface profiles at the project site across the slope failures. The subsurface conditions encountered at the boring locations are shown on the test boring records in Appendix B. Also, the inferred subsurface conditions at the CPT sounding locations are shown on the CPT records in Appendix C. These test boring records and profiles represent our interpretation of the subsurface conditions based on visual examination of field samples and laboratory tests. The lines designating the interfaces between various strata on the test boring records represent the approximate interface locations. The actual transitions between strata may be gradual.

Consistent with the published geologic mapping, the borings and CPT soundings encountered three major natural strata underlying existing 6-inch thick asphalt pavement structure and Fill materials. The natural soils include an upper sand stratum (Nanjemoy, Tn Stratum) overlying Marlboro Clay (Tm Stratum) and Aquaia Formation (Ta Stratum). These strata are briefly described in the following paragraphs.

Existing FILL (F):

This two to six feet thick stratum was encountered typically below the existing asphalt pavement (borings B-1 through B-10) and at borings B-14, B-15 and B-17 (within the vicinity of an abandoned building structure). Existing FILL materials consisted of a heterogeneous mixture of brown to reddish brown Silty Sand, Clayey Sand and Gravels with deleterious materials such as asphalt fragments, decomposed wood and organics. Soft silt and clay materials were locally encountered at boring B-15. The SPT N-values ranged from 3 to 19 blows per foot (bpf) indicating very loose to medium dense, typically loose relative density.

Stratum I: Natural Silty SAND, Clayey SAND, Sandy SILT (Tn Stratum)

This stratum was encountered below existing Fill or occurred as the top stratum in several test borings up to a depth of about 15 feet bgs in the elevated upslope areas. It appears to thin out towards the low lying and downslope areas towards the wetlands and stream (e.g., in the general area borings B-1 and B-4, and from B-13 towards B-16, etc.) It generally consisted of moist, brown, light brown, dark gray, very loose to medium dense Silty Sand (SM), Clayey Sand (SC), coarse Sand (SP) with Gravels, and interbedded with

soft to stiff Sandy Silt (ML) and Sandy Clay (CL) layers. The SPT blow counts ranged from 3 to 12 bpf indicating very loose to medium dense, typically loose relative density. Soils appeared to be slightly plastic.

Stratum II – CLAYS (Tm Stratum)

Marlboro Clay stratum was encountered below the Tn Stratum at each of the exploration locations. It varied in thickness from 15 to 30 feet with the base typically at approximate El. 78 and El. 74; and locally at approximate El. 50 at the lower topographic areas, and up to El. 135 at the higher elevations. It generally consisted of moist to wet, reddish brown, brown, light gray to gray, Lean Clay (CL) with occasional thin lenses of micaceous Silt. Locally, we encountered occasional Fat Clays (CH) within this stratum. The SPT N-values ranged from 3 to 14 bpf indicating generally soft to stiff compactness, typically medium stiff. The moisture content of the tested samples ranged from 14 to 48 percent. The Liquid Limit ranged from 26 to 59 percent with Plasticity Index (PI) ranging between 10 and 30 percent, indicating typically high to very high plasticity soils. We noted, however, that the clay soils appeared to be brittle.

Stratum III – SAND AND SILT (Ta Stratum)

This stratum was encountered below the Marlboro Clay to the boring termination depths. It generally consisted of moist to wet, olive gray, greenish gray to dark gray, Silty Sand (SM) and Sandy Silt (ML) with mica and calcareous shell fragments scattered throughout the stratum. The SPT N-values ranged from 5 to over 100 bpf (characterized by spoon refusals in the cemented layers), indicating generally loose to very dense relative density. The loose zones appeared to occur at the interface with the Marlboro Clay. The relative density appears to be typically medium dense to dense compactness, and/or stiff to hard compactness. The moisture content of the tested samples ranged from 20 to 30 percent, with non-plastic to slight plasticity (PI less than 4 percent).

2.3.5 Groundwater and Cave-in Conditions

We observed and recorded groundwater and cave-in depth information in each boring during drilling (within the drill augers), and several hours after completion of drilling (and removal of the augers). In addition, we have installed a piezometer near Boring B-2 to record long term groundwater levels. Table 2-



1 below provides a summary of groundwater conditions and cave-in depths. Where encountered, groundwater and/or perched water conditions generally occurred at depths between 10 and 60 feet bgs.

Cave-in occurred at depth between 14 and 65 feet bgs following removal of the drill augers. Cave-in may be due to the collapse of soils after removing augers at the completion of drilling. However, in granular soils, cave-in depths may be due to the presence of saturated soil conditions arising from groundwater and/or perched-water conditions.

Because of the presence of clayey and silty nature (characterized by relatively impermeable conditions) within portions of the site soils, site soils have the potential of developing perched water conditions. In addition, seasonal and/or long-term fluctuations of the groundwater levels and/or perched water may occur due to variations in rainfall, evaporation, soil capillary, construction activity, ground conditions and surface runoff, and other site-specific factors, and should be anticipated.

Table 2.1: Summary of Groundwater Condition					
Boring Nos.	Groundwater Levels				Cave-in Depths (ft)
	Depth (ft) (in augers)	Depth (ft) (0 hr)	Depth (ft) (>24 hrs)	Elevation (ft)	
B-1	43.8	57.8	-	11.8	14
B-2	31.2	11.1		63.3	21
Observation Well	-	36.7	37	37.6	-
B-3	48	42	10	69.7	18
B-4	-	59	34.3	63.3	36
B-6	Mud rotary drilling				
B-7	20.5	12	11	104.0	65
B-8	Mud rotary drilling				
B-9	18	17	15.5	105.2	
B-10	Mud rotary drilling				
B-11	Dry	-	-	-	92

Table 2.1: Summary of Groundwater Condition					
Boring Nos.	Groundwater Levels				Cave-in Depths (ft)
	Depth (ft) (in augers)	Depth (ft) (0 hr)	Depth (ft) (>24 hrs)	Elevation (ft)	
B-13	Mud rotary drilling				
B-14	54.8	36	9.8	99.6	25
B-15	67.5	59	10.1	97.8	28
B-16	Mud rotary drilling				
B-17	Mud rotary drilling				

Piezometers

KCI subcontractor, CenKen, installed one piezometer near Boring B-2 on May 13, 2014 to monitor long term groundwater levels. The screen was installed at between 35 to 50 feet below the existing ground surface. A KCI engineer obtained the initial water-level reading on May 13, 2014 using a groundwater monitoring meter. We plan to perform daily readings to monitor the long-term fluctuations of the water table at that location.

We installed and have been monitoring the groundwater levels in general accordance with ASTM D5092. The details of general installation procedures are provided in Appendix B.

2.4 SLOPE MOVEMENT MONITORING

Our subcontractor, CenKen, installed six inclinometer casings from May 9 to May 13, 2014 to monitor further slope movements. We installed the casings at an average depth of 70 feet below the existing slope surface. A KCI engineer commenced obtaining the baseline inclinometer readings from May 12 and 13, 2014 using a probe-type inclinometer. We plan to perform daily inclinometer readings to determine potential progressive slope movements prior to the slope stabilization. We will provide the results of our

slope monitoring along with final recommendations in a brief memorandum within two weeks from our last survey.

We are monitoring the slope movement in general accordance with ASTM D 6230. The details of general installation procedures and typical inclinometer survey procedures are provided in Appendix B.

2.5 LABORATORY TESTING

We performed laboratory testing on representative soil samples (from disturbed jar samples and undisturbed Shelby Tube samples) to confirm visual soils classifications and to determine physical properties of in-situ soils. The laboratory tests were conducted in general accordance with ASTM standards and included the following:

	<u>No. of Tests</u>
• Natural Moisture Content (ASTM D 2216)	42
• Classification Tests, including:	
- Atterberg Limits (ASTM D 4813)	29
- Sieve Analysis (ASTM D 422)	24
• Direct Shear Test (ASTM D 3080)	5
• CIU Triaxial Test (ASTM D 4767)	1
• One-Dimensional Consolidation Test (ASTM D 2435)	1

We have provided details of laboratory testing procedures and the laboratory test results in Appendix C. Due to the slope failure and unstable ground issues associated with the presence of the Marlboro Clay stratum at the project site, we performed laboratory testing to determine shear strength parameters (undrained direct shear, DS and consolidated undrained Triaxial, (CIU) and deformation characteristics (one dimensional consolidation) of the Tm stratum. Table 2-2 provides a summary of the shear strength test results.



Table 2-2: Summary of Shear Strength Results for Marlboro Clay (Tm)

Boring No.	Sample	Test Type	USCS	Cohesion c', (psf)	Friction Angle, °	Moisture Content, (%)	Unit Weight, (pcf)	LL %	PI %	Fines %
B-13	ST-1 (22'-24')	DS	ML	997	29.3	36	115	48	18	78
B-13	ST-2 (28'-30')	DS	CL	473	22.4	32	118	39	14	100
B-14	ST-1 26.5'-28.5')	DS	CL	650	14.2	27	122	38	16	100
B-15	ST-1 (22'-24')	DS	CL	11.3	31	35	117	40	16	90
B-15	ST-1 (22'-24')	CIUC	CL	130	18.4	33	121	40	16	90
B-17	ST-1 (22'-24')	DSR	CL	759	29.7	44	116	47	28	74

*DS=Direct shear testing conducted at 0.01 in/minute shearing rate without residual cycles

**DSR = Direct shear testing conducted at 0.01 in/minute shearing with residual cycles

3.0 GEOTECHNICAL EVALUATIONS

3.1 SLOPE STABILITY ANALYSES

KCI performed preliminary global stability analyses for the pre-existing failure conditions of the slopes. This enabled us to back-calculate the critical shear strength parameters of the Marlboro Clay (Tm Stratum) under marginal stability conditions (defined by Factor of safety, FS = 1.0 or less). Based on the results of the subsurface explorations, we developed a typical subsurface profile for a critical slope section for our analyses as depicted in Appendix D. We have assumed that the phreatic water level was developed in the upper Tn (Stratum I) during slope failure.

We selected preliminary design soil parameters based on the field and laboratory test results, and our experiences with similar soil materials. We used the General Limit Equilibrium/Morgenstein-Price (GLE) method for the slope stability analyses to satisfy both force balances and moment balances of soil slices in order to find the most critical slip surface and the minimum factor of safety (FS) of the slope. We utilized both circular slip search and block slip search for the back analyses. We conducted our slope stability analyses using the software Slide Version 6.029 developed by RocScience Inc. We have analyzed several slope scenarios as part of the back-calculation evaluations using the following laboratory soil parameters and slope conditions as summarized in Table 3.1.

Table 3.1: Definition of Back Analyses Cases		
	Soil Properties: Marlboro Clay (Tm Stratum)	
Assumed Slope Conditions	C' (psf)	ϕ' (°)
A. Groundwater depth at 10 feet and rear tension cracks	130	18
B. Groundwater depth at 10 feet and no tension cracks	130	18
C. Groundwater depth at 5 feet and rear tension cracks	130	18
D. Groundwater depth at 5 feet and no tension cracks	130	18
E. Groundwater depth at 10 feet and rear tension cracks	130	14
F. Groundwater depth at 10 feet and no tension cracks	130	14

Table 3.1: Definition of Back Analyses Cases

Assumed Slope Conditions	Soil Properties: Marlboro Clay (Tm Stratum)	
	C' (psf)	ϕ' (°)
G. Groundwater depth at 5 feet and rear tension cracks	130	14
H. Groundwater depth at 5 feet and no tension cracks	130	14

We have provided detailed of our slope analyses in Appendix D. The results of our preliminary slope stability analyses are summarized in Table 3.2.

Table 3.2: Summary Results of Pre-Failure Slope Analyses

Case	H _w	Tension Cracks Exist	ϕ' (°)	c' (psf)	FS
A	10	Yes	18	130	1.02
B	10	No	18	130	1.13
C	5	Yes	18	130	0.91
D	5	No	18	130	0.98
E	10	Yes	14	130	0.84
F	10	No	14	130	0.97
G	5	Yes	14	130	0.77
H	5	No	14	130	0.78
H _w = Vertical height of water below the existing ground surface FS = Minimum Factor of Safety					

The results of our preliminary analyses confirmed that slope failure likely occurred under fully saturated slope conditions within the overburden Tn stratum and Marlboro Clay as indicated by the laboratory testing data. Pending additional testing, we recommend that residual soil shear strength from the CIUC test (cohesion, c' = 130 psf, friction angle = 18 degrees) be used for the Marlboro Clay in preliminary evaluations of slope stabilization options. Also the groundwater level should be set at 5 feet or less below grade for design stabilization efforts.

3.2 POTENTIAL CAUSES OF THE EXISTING LANDSLIDE

There are several causes such as, geological, morphological, physical and human activity that can render a site susceptible to landslide and ground movements. When such conditions exist, only one trigger is needed to cause the slope to fail/slide. Trigger is an external stimulus such as intense rainfall and storm water infiltration, earthquake shaking, volcanic eruption, storm waves, or rapid stream erosion that caused a near-immediate response in the form of a landslide by rapidly increasing the imposed stresses or by reducing the strength of slope materials due to significant pore pressure developments within saturated soils.

Based on our preliminary site evaluations and analysis and our review of historic information, the geology of the site, in particular the presence of the Marlboro Clay, made it susceptible to landslide and ground settlements. The trigger was intense and rapid infiltration of rainfall that occurred prior to the slope failure.

Our post-failure subsurface explorations confirmed that three geologic formations are present at the site. Of particular concern is the Marlboro Clay which is sandwiched between the upper Nanjemoy and the lower Aquia formations. Historic information (Pomeroy, 1988, *Map Showing Landslide Susceptibility in Maryland, USGS Miscellaneous Field Studies Map MF-2048*) suggests that Marlboro Clay is one of the Coastal Plain geologic formations highly susceptible to slope failures. Localized and mass ground movements associated with slumps and earthflows are known to be associated with Marlboro Clay with numerous slope failures having occurred in south-western and east-central Prince George's County.

During wet periods as rainfall percolates downward through the overlying permeable sandy and silty soils, it encounters the relatively impermeable Marlboro Clay layer. The microstructure of Marlboro clay makes it difficult for water to infiltrate. Thus, infiltrated water will move primarily along the surfaces of the clay layers. Over time, this water may gradually dissipate with little easing of the pore-pressures and causing little or no slope movements. However, during the recent intense and rapid rainfall recorded at the project site, the infiltrated water was not able to quickly dissipate in the Marlboro Clay and generated massive pore-pressure built up in the saturated sediments. These high pore pressures resulted in shear



strength degradation and creating weak subsurface zones with significant reduction in the frictional resistance along the contacts between the saturated soil and the Marlboro Clay. This condition produced new slide surfaces and potentially regenerated existing failure planes leading to the on-going slope failures and landslide at Piscataway Drive.

As depicted on the Subsurface Profiles Figures 4A, 4B and 4C (Appendix A), we have estimated approximate depths of the landslide and slope failure planes based on the test borings and CPT soundings and the residual strengths from laboratory testing. Our visual examination of extracted undisturbed Shelby tube sample ST-1 from boring B-15 provided evidence of a near horizontal failure plane between depths of 23.2 and 23.6 feet bgs, corresponding to approximate El. 85 (See Figure No. 5 in Appendix A). In addition, during drilling at boring B-17, we encountered loss of drilling fluid mud between depth of 25 and 26 feet bgs (approximate El. 85). This may be indicative of a failure plane.

4.0 GEOTECHNICAL RECOMMENDATIONS

4.1 GENERAL

The material within the landslide area has been weakened by the movement of soil mass and has thus lost some amount of shear strength. Also, our test results indicate that pore-pressures have not dissipated, hence, the continual recorded movement. Furthermore, with lots of crack openings within the site, infiltration of water will generate more pore-pressure and further destabilizing the slopes and causing more movement. Thus, the failed slopes have to be repaired immediately.

4.2 SLOPE STABILIZATION OPTIONS

To stabilize the failed slopes, KCI examined several methods and have performed preliminary analyses on three. We are proposing three preliminary alternatives for stabilization of the failed slopes and landslide areas at the project site as presented in Table 4-1. The conceptual designs of the stabilization alternatives are also provided.

As discussed previously, the major geotechnical issue relates the presence of saturated overburden soils overlying the impermeable Marlboro Clay which is known to be susceptible to landslides and slope failures. The interface between the overburden soils and clay strata loses significant frictional resistance when subjected to undrained conditions due to water infiltration leading to pore pressure build-up. The resulting loss of shear strength indicates that there is insufficient resistance along the interface to resist driving forces thus leading to slope instability.

In order to stabilize the slope and mitigate ground movements, measures should be taken to provide additional resistance and reduce slope driving forces risk to minimize the risk to public properties and life. Note that the proposed slope stabilization schemes are designed to stabilize the upper slope portions above Piscataway Drive roadway and protect the roadway. Note that we did not provide stabilization for

the slope portion further downhill toward the river due to the anticipated lower risk to public properties and lives.

Table 4.1: Summary of Proposed Preliminary Slope Stabilization Options		
Option	Grade & Backfill	Structural Element Support
1	Backfill slopes (3H:1V) above roadway and support using an 8-foot high soldier-lagging wall	Drilled Shaft Foundation and Micropile (Mini-pile) Anchors
2	Limited Slope Regrading	Drilled Shaft and Micropile
3	Limited Slope Regrading	Micropile

Option 1: This alternative includes a combination of ground stabilization partial backfill and mid-slope stabilization and protection. This method involves the installation of two rows of drilled shaft foundations along both sides of the Piscataway Drive, a retaining wall with backfill, and two rows of micropiles (mini-piles) near the existing head scarp. These reinforcements will be extended beyond the failure surfaces. This stabilization is associated with the installation of structural elements with high strength, which introduce forces to oppose movement and support the sliding mass, resulting in stabilization of the landslide. Partial slope backfilling supported with a retaining wall along the roadway to stabilize the toe of slope. We have provided details of the conceptual design on Figure D-9 in Appendix D.

Option 2: This alternate involves ground stabilization using drilled shafts along the roadway and slope reinforcement using micropiles along the entire western side to reinforce the failed slopes with limited regrading. On the eastern slopes, we recommend one row drilled shafts installed beyond the failure surface and embedded in Ta Stratum. We have provided details of the conceptual design on Figure D-10 in Appendix D.

Option 3: This alternate is similar to Option 2; however, we use only micropiles for both ground stabilization and reinforcement with limited regrading. The method involves the installation of micropiles throughout the slopes on both sides of Piscataway Drive. The mini piles will be extended beyond the failure surface to a minimum depth of 50 feet into Ta Stratum. We have provided details of the conceptual design on Figure D-11 in Appendix D.

Our analyses indicate that each of the options will adequately stabilize the slopes and mitigate additional movements within the vicinity of improvement. However, the drilling and grouting equipment used for micropile installation is relatively small and can be mobilized in constrained and restrictive areas that would prohibit the entry of conventional heavy drilled shaft-installation equipment. In addition, micropile installation will not be impacted by overhead power lines or other obstructions as are conventional drilled shaft systems. The equipment can be mobilized up steep slopes and in remote locations. Also, drilling and grouting procedures associated with micropile installations will not cause significant site disturbance or damage to adjacent existing structures and buried utility mains when proper drilling and grouting procedures are used.

We anticipate that the resulting ground movements indicated by the inclinometer readings will have significant implications for the slope rehabilitation options. Therefore, we will revise the proposed stabilization options accordingly, and recommend that additional detail analyses and design, constructability evaluations and cost analyses be performed for each option as part of the final design purposes.

4.3 UTILITY COORDINATION AND RECONSTRUCTION RECOMMENDATIONS

The Utility Coordination efforts should continue and should include meeting and talking with each utility company to discuss the impacts to their facilities and potential mediation once the slope is stabilized.

WSSC Facilities: The existing eight-inch Ductile Iron Pipe (DIP) water main (12/20/02 Contract) and the eight-inch Concrete Sanitary Line (6/1/70 Built date) will need to be replaced within the proposed length



of the roadway reconstruction (approximately 1,500 linear feet). KCI recommends that both lines be replaced within the existing footprint location in relation to the existing roadway. Prior to the soil failure the water and sanitary house connections ran under the failing slope; these connections collapsed during the failure event. KCI recommends that after the soil stabilization the replacement design should incorporate the use of a carrier pipe. A design will avoid the need to have the services running through the selected stabilized slope treatment.

KCI recommends the proposed water main and sanitary sewer replacement work be performed under the same construction contract.

Electric, Cable TV (CATV) and Telephone Facilities: PEPCO previously maintained a pole line along the southern edge of paving of Piscataway Drive which carried a single phase primary electric cables as well as third parties; COMCAST and Verizon cables. Temporarily the electric line has been de-energized and picked up from the broken poles and lifted to avoid danger to the crews working in the area. PEPCO is evaluating a temporary and permanent solution based upon the method and implementation of the slope stabilization.

Initially, it is anticipated that the impacted single phase pole line be reconstructed in a similar alignment and fashion as the system prior to the slope failure. The downstream and upstream poles should be evaluated in relation for vertical lift and tension impact sustained during the event and change pending line and grade. KCI recommends the collapsed service pole which was carrying the electric, CATV and telephone underground services be relocated along the common driveway of the impacted properties to avoid services running through the selected stabilized slope treatment.

4.4 ENVIRONMENTAL COORDINATION

On May 12, 2014, KCI performed wetland delineation within the vicinity of Piscataway Drive in Fort Washington, Maryland. KCI identified one palustrine forested wetland at the base of the slope below Piscataway Drive, as well as two associated stream channels, designated intermittent and perennial, respectively. KCI contacted the Maryland Department of the Environment (MDE) and the US Army Corps of Engineers on May 16, 2014 and the agencies concurred that the work constitutes an emergency.



MDE specified that if any access through regulated resources is needed in order to complete the repairs, a Joint Permit Application (JPA) must be submitted within 30 days. Impacts to wetlands and waterways should be minimized to the amount necessary to repair the slope. KCI contacted the Chesapeake Critical Areas Commission (CAC) on May 15, 2014 to make them aware of the ongoing emergency activities. A CAC letter will be prepared during final design.

4.5 ROADWAY RECONSTRUCTION AFTER THE SLOPE STABILIZATION PROCESS HAS BEEN COMPLETED

Utilizing the topographic survey, KCI will develop a baseline that will closely match the centerline of the existing roadway. This baseline will serve as the centerline for the reconstructed roadway. KCI will generate and evaluate the existing roadway profile since portions of the roadway have settled significantly. We will generate a revised roadway profile for the posted 25 mph per American Association of State Highway and Transportation Officials (AASHTO) – A policy on Geometric Design of Highways and Streets (Chapter 5: Local Roads and Streets). KCI will develop a typical Rural Secondary Residential roadway section for a 22-foot wide crowned roadway with 2% roadway cross-slopes. We will vary roadside grading to closely match the condition prior to the slope and roadway failure to reduce impacts to the existing residences. KCI will generate existing ground cross-sections with the proposed new roadway section superimposed to develop grading limits and earthwork requirements. We will place impermeable side ditches where necessary to divert the sheet flow of water away from the roadway into existing or proposed cross pipes.

KCI anticipates that during construction, once the slopes are stabilized (and all major construction equipment is no longer required to utilize the existing roadway), the existing pavement will be thoroughly broken up, scarified or removed. The embankment and subgrade will be placed along with any ditch and required cross pipes (existing cross pipes shall be cleaned). We will use the Prince George's County pavement section, or provide a recommended pavement design including a six-inch underdrain along both roadway edges. The underdrain will be outlet to the fill slopes. Guardrail will be required along the east side of the roadway for most if not the entire length of the reconstruction. Curbing may also be placed



along the east side of the roadway to divert water away from the fill slopes to curb openings and stabilized slope channels.

5.0 STRATEGY FOR MOVING FORWARD

This report provides a preliminary concept design prepared after reviewing the feasibility of several options. We have developed the recommended concept to an approximate 20% design stage. KCI will now work with Prince George's County DPW&T to consider option for moving forward with the recommendation contained in this report.

6.0 BASIS OF RECOMMENDATIONS

General

1. This report has been prepared to aid in the evaluation for the proposed construction described in this report. Adequate recommendations have been provided to serve as a basis for design and preparation of plans and specifications. The opinions, conclusions, and recommendations contained in this report are based upon our professional judgment and generally accepted principles of geotechnical engineering. Inherent to these are the assumptions that the earthwork and foundation construction should be monitored and tested under the guidance of a geotechnical engineer licensed in the State of Maryland or his representative.

Explorations

2. The analyses and recommendations provided are, of necessity, based on project information available at the time of the actual writing of the report, including existing site, surface and subsurface conditions that existed at the time the exploratory borings were drilled. Further assumption has been made that the limited exploratory borings, in relation to both the lateral extent of the site and to depth, are representative of general conditions across the site. The nature and extent of variations between these explorations may not become evident until further explorations and construction. If variations from anticipated conditions then appear evident, it will be necessary to revise the recommendations in this report.
3. The soil strata described in the text and indicated on the subsurface profiles are intended to convey generalized trends in subsurface conditions. Boundaries between strata are approximate and idealized, and developed by interpretations of widely spaced explorations and sampling; actual soils transitions are probably more erratic. Refer to boring logs for specific information.
4. Groundwater level readings have been made in the drill holes at times and under conditions stated on the boring logs. These data have been reviewed and interpretations have been made in this report. Fluctuations in the level of the ground water may occur due to variations in rainfall, temperature, and other factors occurring since the time measurements were made.

Review

5. This report has been prepared based on plans and description of the proposed construction cited herein. In the event that any changes in the nature, design or location of the proposed construction, the conclusions and recommendations contained in this report shall not be considered valid unless the changes are reviewed and conclusions of this report modified or verified in writing by KCI. We recommend that KCI be provided the opportunity for a general review of design and specifications so that our recommendations may be properly interpreted and implemented in the design specifications.




Uses of Report

6. This final report has been prepared for the exclusive use of Prince Georges County Government and other members of the design team for specific application of the Engineering Design services for the **Piscataway Drive Slope Failure**, Fort Washington, Maryland. Our professional services were performed in accordance with generally accepted soil and foundation engineering principles and practices; no other warranty, expressed or implied, is made. KCI assumes no responsibility for interpretations made by others on the work performed by KCI.
7. In the event the County proceeds forward with construction, this report is for design purposes only and is not sufficient to prepare an accurate bid. Contractors wishing a copy of the report may secure it with the understanding that its scope is limited to design considerations only. We recommend that this report be made available in its entirety including attachments and appendices to contractors for informational purposes only. The project plans or specifications should include the following note:

A geotechnical report has been prepared for this project by KCI Technologies, Inc. This report is for informational purposes only and shall not be considered as part of the contract documents. The opinions and conclusions of KCI represent our interpretation of the subsurface conditions and the planned construction at the time of the report preparation.

FIGURES:
**SITE LOCATIONS PLAN, BORING LOCATION PLAN, SUBSURFACE
PROFILES, AND ROADWAY PLANS AND CROSS SECTIONS**





**ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS**
KCI
 TECHNOLOGIES

936 Ridgebrook Rd.
 Sparks, MD 21152
 410-316-7800 | Fax 410-316-7817

SITE LOCATION MAP				
PISCATAWAY DRIVE SLOPE FAILURE				
FORT WASHINGTON, PRINCE GEORGES COUNTY, MARYLAND				
DRAWN BY	APPROVED BY	SCALE	DATE	KCI JOB NUMBER
LSG	KA	NTS	MAY 2014	07100627.W

Figure No.
1



Piscataway Drive Slope Failure

Figure 2: Exploration Plan

KCI TECHNOLOGIES INC.

936 Ridgebrook Road, Sparks, MD 21152 Phone 410-527-4403 Fax 420-316-7935




CPT




SPT

IN-1 Inclinometer Installation

PZ-1 Piezometer Installation



ArcGIS Online Microsoft Bing Maps Premium Subscription



ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS

936 Ridgebrook Rd.
Sparks, MD 21152
410-316-7800 | Fax 410-316-7817

REGIONAL GEOLOGY MAP PISCATAWAY DRIVE SLOPE FAILURE PRINCE GEORGE'S COUNTY, MD

Figure No.

3A


DRAWN BY
SS

APPROVED BY
KA

SCALE
NTS

DATE
May 2014

KCI JOB NUMBER
07100627.W




Source: Esri, DigitalGlobe, GeoEye, i-cubed, USDA, USGS, AEX, Getmapping, Aerogrid, IGN, IGP, swisstopo, and the GIS User Community

Piscataway Drive Slope Failure


Figure 3B: Site Geology Map

KCI TECHNOLOGIES INC.

936 Ridgebrook Road, Sparks, MD 21152 Phone 410-527-4403 Fax 420-316-7935



KCI 11X17 WLOG02 PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/18/14



-x-x-x-x- APPROXIMATE DEPTH TO FAILURE SURFACE BASED ON TEST BORINGS & CPT SOUNDINGS


USCS SOIL KEY		GW		SW		
		GP		SP		
		GM		SM		
		GC		SC		



ENGINEERS AND PLANNERS
936 Ridgebrook Road
Sparks, MD 21152-9390
(410) 316-7800

Title: SUBSURFACE PROFILE A-A PISCATAWAY DR SLOPE FAILURE			Figure No. 4A
Drawn: KBA	Approved: KOA	Date: 5/18/14	KCI Job No. 07100627W


KCI 11X17 WLOG2 PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/18/14



-X-X-X-X- APPROXIMATE DEPTH TO FAILURE SURFACE BASED ON TEST BORINGS & CPT SOUNDINGS

USCS SOIL KEY	GW	GP	GM	GC	SW	SP	SM	SC	ML	MH	CL	CH	OL	OH	FILL	CWR
KCI TECHNOLOGIES																
ENGINEERS AND PLANNERS 936 Ridgebrook Road Sparks, MD 21152-9390 (410) 316-7800																
Title: SUBSURFACE PROFILE B-B PISCATAWAY DR SLOPE FAILURE																
Drawn: KBA Approved: Date: 5/18/14																
Figure No. 4B KCI Job No. 07100627W																

KCI 11X17 WLOG02 PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/18/14



-x-x-x-x- APPROXIMATE DEPTH TO FAILURE SURFACE BASED ON TEST BORINGS & CPT SOUNDINGS

USCS SOIL KEY	GW	GP	GM	GC	SW	SP	SM	SC	ML	MH	CL	CH	OL	OH	FILL	CWR



KCI
TECHNOLOGIES

ENGINEERS AND PLANNERS
936 Ridgebrook Road
Sparks, MD 21152-9390
(410) 316-7800

Title: SUBSURFACE PROFILE C-C PISCATAWAY DR SLOPE FAILURE			Figure No. 4C
Drawn: KBA	Approved: KOA	Date: 5/18/14	KCI Job No. 07100627W

16570-0
 PISCATAWAY SLOPE
 FAILURE CUTRIAX
 B-15/ST-1
 22'0" - 24'0"



ENGINEERS
 PLANNERS
 SCIENTISTS
 CONSTRUCTION MANAGERS

KCI
 TECHNOLOGIES

936 Ridgebrook Rd.
 Sparks, MD 21152
 410-316-7800 | Fax 410-316-7817

POTENTIAL FAILURE PLANE IN BORING B-15

PISCATAWAY DRIVE SLOPE FAILURE

FORT WASHINGTON, PRINCE GEORGES COUNTY, MARYLAND

Figure No.

5

DRAWN BY
 LSG

APPROVED BY
 KA

SCALE
 NTS

DATE
 MAY 2014

KCI JOB NUMBER
 07100627.W

**TEST BORING LOGS & CPT SOUNDING RESULTS
FIELD OPERATIONS PROCEDURES, SLOPE AND WATER-LEVEL
MONITORING PROCEDURES**



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **69.61 (ft)**

TEST BORING LOG

B-01


SHEET **1** OF **2**

Driller: **Ron/CenKen** Method: **HSA** Casing Length: **59 ft** Date Begun: **5/6/2014**
 KCI Representative: **TA** Hammer Type: **Automatic** Casing Diameter: **3.25** Date Completed: **5/7/2014**

Groundwater Levels (feet)

0 hour: 57.8 ▽

24 hours: _____





PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **69.61 (ft)**

TEST BORING LOG

B-01

SHEET **2** OF **2**


Driller: **Ron/CenKen** Method: **HSA** Casing Length: **59 ft** Date Begun: **5/6/2014**

KCI Representative: **TA** Hammer Type: **Automatic** Casing Diameter: **3.25** Date Completed: **5/7/2014**

Groundwater Levels (feet)

0 hour: 57.8 ▽

24 hours: _____



KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **74.38 (ft)**

TEST BORING LOG


B-02

SHEET **1** OF **2**

Driller: **Ron/CenKen** Method: **HSA** Casing Length: **59 ft** Date Begun: **5/7/2014**
 KCI Representative: **TA** Hammer Type: **Automatic** Casing Diameter: **3.25** Date Completed: **5/9/2014**

Groundwater Levels (feet)

0 hour: 11.1 ▽
 24 hours: _____



KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **74.38 (ft)**

TEST BORING LOG

B-02

SHEET **2** OF **2**

Driller: Ron/CenKen	Method: HSA	Casing Length: 59 ft	Date Begun: 5/7/2014
KCI Representative: TA	Hammer Type: Automatic	Casing Diameter: 3.25	Date Completed: 5/9/2014

Groundwater Levels (feet)

0 hour: 11.1 ▽

24 hours: _____

DEPTH (ft)	SOIL CLASSIFICATION AND REMARKS SEE KEY SYMBOL SHEET FOR EXPLANATION OF SYMBOLS AND ABBREVIATIONS BELOW.	LITHOLOGY	ELEV (ft)	IDNET	TYPE	SAMPLES				PLASTIC M.C. LIQUID				
						N-COUNT				I - - - - - I				
						1st 6"	2nd 6"	3rd 6"	4th 6"	□ FINES (%)				
						REC RQD				● SPT (bpf)				
40	Moist, dark gray, medium dense to dense, Silty SAND, with Shell fragments (SM)		35	S-12	⊗	5-6-7-7	N = 13	REC=18"		20	40	60	80	100
45			30	S-13	⊗	4-6-6-8	N = 12	REC=18"		20	40	60	80	100
50			25	S-14	⊗	2-2-2-2	N = 4	REC=18"		20	40	60	80	100
55			20	S-15	⊗	100/5.8"		REC=5"		20	40	60	80	100
60	- With cemented Clay		15	S-16	⊗	3-4-13-9	N = 17	REC=18"		20	40	60	80	100
65	Boring terminated at 61 ft. bgs		10							20	40	60	80	100
70			5							20	40	60	80	100
75			0							20	40	60	80	100

Notes:

- 1) Water encountered in augers at 10 feet bgs during drilling on 5/7/14, and at 31.2 feet bgs after drilling on 5/9/14
- 2) Groundwater encountered at 11.1 feet bgs after pulling augers on 5/9/14.
- 2) Cave-in occurred at 21 feet bgs 48 hours after drilling.
- 3) 1-1/4" PVC groundwater observation well (OW-1) installed on 5/13/14 at a 5-foot offset from B-2 to a depth of 50 feet.
- 4) Groundwater encountered in observation well at 36.7 feet bgs after installation.



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **79.66 (ft)**

TEST BORING LOG

B-03

SHEET **1** OF **2**


Driller: **Jerry/Hillis Carnes HSA** Method: **HSA** Casing Length: **58.5 ft** Date Begun: **5/8/2014**

KCI Representative: **SS** Hammer Type: **Automatic** Casing Diameter: **3.25** Date Completed: **5/8/2014**

Groundwater Levels (feet)

0 hour: 42 ▽

24 hours: 10 ▽



KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **79.66 (ft)**

TEST BORING LOG

B-03

SHEET **2** OF **2**

Driller: **Jerry/Hillis Carnes** Method: **HSA** Casing Length: **58.5 ft** Date Begun: **5/8/2014**
 KCI Representative: **SS** Hammer Type: **Automatic** Casing Diameter: **3.25** Date Completed: **5/8/2014**

Groundwater Levels (feet)

0 hour: 42 ▽
 24 hours: 10 ▼

DEPTH (ft)	SOIL CLASSIFICATION AND REMARKS SEE KEY SYMBOL SHEET FOR EXPLANATION OF SYMBOLS AND ABBREVIATIONS BELOW.	LITHOLOGY	ELEV (ft)	SAMPLES				PLASTIC M.C. LIQUID ├───┴───▲───┴───┤							
				IDNET	TYPE	N-COUNT				□ FINES (%) ● SPT (bpf)					
						1st 6"	2nd 6"	3rd 6"	4th 6"						
						REC RQD									
						REC=8"				20 40 60 80 100					
▽	Moist, brown, hard, cemented SILT, with Shell fragments (ML)														
45	Moist, gray, very stiff, Sandy SILT, with Shells (ML) - with cemented Silt		35	S-21	⊗		7-8-8 N = 16 REC=8"								45
50	Moist, olive gray, medium dense, Silty SAND, with Shells (SM)		30	S-22	⊗		3-5-7 N = 12 REC=24"								50
55	Moist, dark gray, medium dense, Silty SAND, with Shells (SM)		25	S-23	⊗		4-6-8 N = 14 REC=24"								55
60	Wet, olive gray and brown, very stiff, Sandy SILT, with Shells (ML)		20	S-24	⊗		6-9-13 N = 22 REC=14"								60
	Boring terminated at 60.5 ft. bgs														
65	Notes: 1) Groundwater encountered in augers at 48 ft bgs during drilling, and 42 ft bgs after drilling. 2) Groundwater encountered at 10 ft bgs 48 hrs after drilling. 3) Cave-in occurred at 48 ft bgs after drilling and 17.6 ft bgs 48 hrs after drilling.		15												65
70			10												70
75			5												75
			0												



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **97.61 (ft)**

TEST BORING LOG

B-04

SHEET **1** OF **2**


Driller: **James/CenKen** Method: **HSA** Casing Length: **59 ft** Date Begun: **5/9/2014**

KCI Representative: **TA** Hammer Type: **Automatic** Casing Diameter: **3.25** Date Completed: **5/9/2014**


Groundwater Levels (feet)

0 hour: 59 ▽

96 hours: 34.3 ▼



KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14





PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **112.88 (ft)**

TEST LOG

B-06

SHEET **1** OF **3**

Driller:
James/CenKen

Method:
Mud Rotary

Casing Length:
79 ft

Date Begun: **5/9/2014**

Groundwater Levels (feet)

KCI Representative:
SS


Hammer Type:
Automatic

Casing Diameter:
5

Date Completed: **5/11/2014**

0 hour: _____

24 hours: _____



KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **112.88 (ft)**

TEST LOG

B-06

SHEET **2** OF **3**

Driller:
James/CenKen

Method:
Mud Rotary

Casing Length:
79 ft

Date Begun: **5/9/2014**

Groundwater Levels (feet)

KCI Representative:
SS


Hammer Type:
Automatic

Casing Diameter:
5

Date Completed: **5/11/2014**

0 hour: _____

24 hours: _____



KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **112.88 (ft)**

TEST LOG

B-06

SHEET **3** OF **3**

Driller:
James/CenKen

Method:
Mud Rotary

Casing Length:
79 ft

Date Begun: **5/9/2014**

Groundwater Levels (feet)

0 hour: _____

24 hours: _____

KCI Representative:
SS

Hammer Type:
Automatic

Casing Diameter:
5

Date Completed: **5/11/2014**

DEPTH (ft)	SOIL CLASSIFICATION AND REMARKS SEE KEY SYMBOL SHEET FOR EXPLANATION OF SYMBOLS AND ABBREVIATIONS BELOW.	LITHOLOGY	ELEV (ft)	SAMPLES				PLASTIC M.C. LIQUID						
				IDNET	TYPE	N-COUNT				I - - - - - ▲ - - - - - I				
						1st 6"	2nd 6"	3rd 6"	4th 6"	<input type="checkbox"/> FINES (%)				
										● SPT (bpf)				
						REC RQD		20	40	60	80	100		
						N = 19 REC=18"								
	Boring terminated at 80.5 ft. bgs		30											
85	Notes: 1) Groundwater not recorded in borehole due to mud rotary drilling. 2) Inclinator No. IN-4 installed in borehole to a depth of 80.5 feet.		25									85		
90			20									90		
95			15									95		
100			10									100		
105			5									105		
110			0									110		
115			-5									115		



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **115.01 (ft)**

TEST BORING LOG

B-07

SHEET **1** OF **3**


Driller: **Jerry/Hillis Carnes** Method: **HSA** Casing Length: **88.5 ft** Date Begun: **5/9/2014**


KCI Representative: **SS** Hammer Type: **Automatic** Casing Diameter: **3.25** Date Completed: **5/9/2014**

Groundwater Levels (feet)

0 hour: 12 ▽

48 hours: 11 ▽







PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **115.01 (ft)**

TEST BORING LOG

B-07

SHEET **3** OF **3**

Driller: Jerry/Hillis Carnes	Method: HSA	Casing Length: 88.5 ft	Date Begun: 5/9/2014
KCI Representative: SS	Hammer Type: Automatic	Casing Diameter: 3.25	Date Completed: 5/9/2014

Groundwater Levels (feet)

0 hour: 12
48 hours: 11

DEPTH (ft)	SOIL CLASSIFICATION AND REMARKS SEE KEY SYMBOL SHEET FOR EXPLANATION OF SYMBOLS AND ABBREVIATIONS BELOW.	LITHOLOGY	ELEV (ft)	IDNET	TYPE	SAMPLES				PLASTIC M.C. LIQUID				
						N-COUNT				I - - - - - I				
						1st 6"	2nd 6"	3rd 6"	4th 6"	□ FINES (%) ● SPT (bpf)				
						REC RQD REC=9				20	40	60	80	100
85	Moist, olive gray, very stiff to hard, Sandy SILT, with shell fragments and mica (ML)		30	S-32	⊗	10-12-50/4" N = 112 REC=9								85
90	Moist, olive gray, dense, Silty SAND, with mica and shells (SM)		25	S-33	⊗	17-18-21 N = 39 REC=18								90
95	Boring terminated at 90 ft. bgs													
100	Notes: 1) Water encountered at 20.5 feet bgs within auger after drilling, at 12 feet bgs after pulling augers. 2) Ground water encountered at 11 feet after 48hrs 3) Cave-in occurred at 65 feet bgs after drilling.													
105			10											105
110			5											110
115			0											115



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **120.09 (ft)**

TEST LOG

B-08

SHEET **1** OF **3**


Driller: **James/CenKen** Method: **Mud Rotary** Casing Length: **81 ft** Date Begun: **5/13/2014**

KCI Representative: **TA** Hammer Type: **Automatic** Casing Diameter: **5** Date Completed: **5/13/2014**

Groundwater Levels (feet)

0 hour: _____

24 hours: _____





PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **120.09 (ft)**

TEST LOG

B-08

SHEET **2** OF **3**

Driller:
James/CenKen

Method:
Mud Rotary

Casing Length:
81 ft

Date Begun: **5/13/2014**

Groundwater Levels (feet)

KCI Representative:
TA


Hammer Type:
Automatic

Casing Diameter:
5

Date Completed: **5/13/2014**

0 hour: _____

24 hours: _____



KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **120.09 (ft)**

TEST LOG

B-08

SHEET **3** OF **3**

Driller: **James/CenKen** Method: **Mud Rotary** Casing Length: **81 ft** Date Begun: **5/13/2014**
 KCI Representative: **TA** Hammer Type: **Automatic** Casing Diameter: **5** Date Completed: **5/13/2014**

Groundwater Levels (feet)

0 hour: _____

24 hours: _____

DEPTH (ft)	SOIL CLASSIFICATION AND REMARKS SEE KEY SYMBOL SHEET FOR EXPLANATION OF SYMBOLS AND ABBREVIATIONS BELOW.	LITHOLOGY	ELEV (ft)	SAMPLES				PLASTIC M.C. LIQUID						
				IDNET	TYPE	N-COUNT				<div> <div> <div></div> <div></div> </div> <div> <div></div> <div></div> </div> </div>				
						1st 6"	2nd 6"	3rd 6"	4th 6"					
						REC RQD								
	Moist, light to dark gray, very dense, Silty SAND, with Shells and cemented layers (SM)			S-30	X	13-48-50/5" N = 148 REC=17"				<div> <div> <div></div> <div></div> </div> <div> <div></div> <div></div> </div> </div>				
85	Boring terminated at 82.5 ft. bgs Notes: 1) Groundwater not recorded in borehole due to mud rotary drilling. 2) Inclinator No. IN-6 installed in borehole to a depth of 82.5 feet.		35							<div> <div> <div></div> <div></div> </div> <div> <div></div> <div></div> </div> </div>				
90			30							<div> <div> <div></div> <div></div> </div> <div> <div></div> <div></div> </div> </div>				
95			25							<div> <div> <div></div> <div></div> </div> <div> <div></div> <div></div> </div> </div>				
100			20							<div> <div> <div></div> <div></div> </div> <div> <div></div> <div></div> </div> </div>				
105			15							<div> <div> <div></div> <div></div> </div> <div> <div></div> <div></div> </div> </div>				
110		10								<div> <div> <div></div> <div></div> </div> <div> <div></div> <div></div> </div> </div>				
115		5								<div> <div> <div></div> <div></div> </div> <div> <div></div> <div></div> </div> </div>				



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **120.69 (ft)**

TEST BORING LOG

B-09

SHEET **1** OF **3**

Driller: **Jerry/Hillis Carnes** Method: **HSA** Casing Length: **83.5 ft** Date Begun: **5/12/2014**

KCI Representative: **SS** Hammer Type: **Automatic** Casing Diameter: **3.25** Date Completed: **5/12/2014**


Groundwater Levels (feet)

0 hour: 17 ▽

24 hours: 15.5 ▼

DEPTH (ft)	SOIL CLASSIFICATION AND REMARKS SEE KEY SYMBOL SHEET FOR EXPLANATION OF SYMBOLS AND ABBREVIATIONS BELOW.	LITHOLOGY	ELEV (ft)	IDNET	TYPE	SAMPLES				PLASTIC M.C. LIQUID				
						N-COUNT				REC	RQD	FINES (%)	SPT (bpf)	
						1st 6"	2nd 6"	3rd 6"	4th 6"					
	6" ASPHALT		120	S-1		8-9-10								
	FILL Sampled As:					N = 19								
	Moist, brown, loose to medium dense, Silty SAND, with Gravel and Asphalt (SM)			S-2		9-6-3-4								
						N = 9								
				S-3		REC=3								
5	Moist, dark brown, medium stiff to stiff, Silty CLAY, trace Gravel and Organics (CL-ML)		115	S-4		6-3-2-4								5
						N = 5								
				S-5		REC=18								
	Moist, reddish brown, medium stiff to stiff, Lean CLAY, little Sand, trace Gravel (CL)					3-5-4-5								
				S-6		N = 9								
10	PP = 1tsf		110	S-7		REC=0								
	PP = 2tsf					2-3-3-5								
				S-8		N = 6								
	Moist, light gray, reddish brown, stiff, Lean CLAY (CL)					REC=24								
15			105	S-9		1-4-6-8								
	Moist, light gray and reddish brown, soft, Sandy SILT (ML)					N = 10								
				S-10		REC=24								
						4-6-8-9								
				S-11		N = 14								
						REC=24								
				S-12		4-5-7-8								
						N = 12								
				S-13		REC=24								
20	Wet, light gray, very soft to soft, Lean CLAY with Sand (CL)		100	S-14		2-2-2-4								
						N = 4								
				S-15		REC=24								
	PP = 0.25tsf													
25	PP = 0.5tsf		95	S-16		REC=23								
						1-1-2-2								
				S-17		N = 3								
						REC=15								
	PP = 0.25tsf			S-18		1-1-2-2								
						N = 3								
				S-19		REC=24								
						1-2-2-2								
						N = 4								
				S-20		REC=24								
						1-1-1-1								
				S-21		N = 2								
						REC=15								
				S-22		1-1-2-2								
						N = 3								
				S-23		REC=24								
30	Wet, reddish brown, medium stiff to stiff, Lean CLAY (CL)		90	S-24		2-2-3-4								
						N = 5								
				S-25		REC=24								
	PP = 0.75tsf					2-3-4-5								
	PP = 1.75tsf			S-26		N = 7								
	PP = 1.25tsf					REC=15								
				S-27		2-3-4-5								
						N = 7								
				S-28		REC=24								
35	Wet, light gray, very stiff, CLAY (CL)		85	S-29		3-4-5-5								
						N = 9								
				S-30		REC=24								
						3-4-5-8								
						N = 9								

KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14





PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **120.69 (ft)**

TEST BORING LOG

B-09

SHEET **3** OF **3**

Driller: **Jerry/Hillis Carnes** Method: **HSA** Casing Length: **83.5 ft** Date Begun: **5/12/2014**

KCI Representative: **SS** Hammer Type: **Automatic** Casing Diameter: **3.25** Date Completed: **5/12/2014**

Groundwater Levels (feet)

0 hour: 17 ▽

24 hours: 15.5 ▼

DEPTH (ft)	SOIL CLASSIFICATION AND REMARKS SEE KEY SYMBOL SHEET FOR EXPLANATION OF SYMBOLS AND ABBREVIATIONS BELOW.	LITHOLOGY	ELEV (ft)	IDNET	TYPE	SAMPLES				PLASTIC M.C. LIQUID				
						N-COUNT				----- ----- ----- ----- -----				
						1st 6"	2nd 6"	3rd 6"	4th 6"	□ FINES (%)				
						REC	RQD			● SPT (bpf)				
						REC=11				20	40	60	80	100
	Moist, olive gray, dense, Silty SAND, with Shells and Mica (SM)		40											
				S-29	50/4"									
					REC=4									
85			35											85
	Boring terminated at 85 ft. bgs													
90	Notes: 1) Water encountered at 18 ft bgs during drilling, 17 ft bgs after drilling, 15.5 ft bgs after 24 hrs at completion of drilling. 2) Cave-in occurred at 54.5 ft bgs after drilling, and at 46 ft bgs 24 hrs after drilling.		30											90
95			25											95
100			20											100
105			15											105
110			10											110
115			5											115



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **125.07 (ft)**

TEST LOG

B-10

SHEET **1** OF **3**


Driller: **Ron/CenKen** Method: **Mud Rotary** Casing Length: **80 ft** Date Begun: **5/14/2014**

KCI Representative: **TA** Hammer Type: **Automatic** Casing Diameter: **5** Date Completed: **5/14/2014**

Groundwater Levels (feet)

0 hour: _____

24 hours: _____



KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **125.07 (ft)**

TEST LOG

B-10

SHEET **2** OF **3**


Driller: **Ron/CenKen** Method: **Mud Rotary** Casing Length: **80 ft** Date Begun: **5/14/2014**

KCI Representative: **TA** Hammer Type: **Automatic** Casing Diameter: **5** Date Completed: **5/14/2014**

Groundwater Levels (feet)

0 hour: _____

24 hours: _____





PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **178.50 (ft)**

TEST BORING LOG

B-11

SHEET **1** OF **3**

Driller: **Jerry/Hillis Carnes** Method: **HSA** Casing Length: **98.5 ft** Date Begun: **5/13/2014**

KCI Representative: **SS** Hammer Type: **Automatic** Casing Diameter: **3.25** Date Completed: **5/13/2014**

Groundwater Levels (feet)

0 hour: Dry

24 hours:

DEPTH (ft)	SOIL CLASSIFICATION AND REMARKS SEE KEY SYMBOL SHEET FOR EXPLANATION OF SYMBOLS AND ABBREVIATIONS BELOW.	LITHOLOGY	ELEV (ft)	IDNET	TYPE	SAMPLES				PLASTIC M.C. LIQUID				
						N-COUNT				I - - - - - I				
						1st 6"	2nd 6"	3rd 6"	4th 6"	□ FINES (%) ● SPT (bpf)				
						REC	RQD			20	40	60	80	100
	1" TOPSOIL													
	Dry to moist, gray and brown, medium stiff, Sandy CLAY, trace Gravel (CL)			S-1		1-3-3-3								
						N = 6								
						REC=12								
	Damp, gray and brown, soft, Lean CLAY, trace Gravel (CL)		175	S-2		1-1-2-3								
						N = 3								
						REC=12								
5	Dry, reddish brown, stiff, Lean CLAY, trace Gravel and Sand (CL)			S-3		3-4-6-6								5
						N = 10								
						REC=18								
			170	S-4		2-5-5-8								
						N = 10								
						REC=12								
10	Moist, light gray, stiff, Sandy SILT (ML)			S-5		3-5-6-5								10
						N = 11								
						REC=12								
	Damp, brown to reddish brown, medium dense, Clayey SAND with Gravel (SC)			S-6		3-6-7-9								
						N = 13								
						REC=4								
	Damp, light gray with reddish brown, stiff, Lean CLAY (CL)		165	S-7		3-6-9-10								
						N = 15								
						REC=24								
15	Dry, light gray with yellowish brown, soft to stiff, Sandy SILT (ML)			S-8		3-5-6-9								15
						N = 11								
						REC=24								
	- Moist		160	S-9		2-5-5-6								
						N = 10								
						REC=12								
20				S-10		2-3-3-5								20
						N = 6								
						REC=24								
				S-11		2-3-5-5								
						N = 8								
						REC=24								
			155	S-12		2-2-2-3								
						N = 4								
						REC=24								
25	- With iron nodules			S-13		1-2-2-3								25
						N = 4								
						REC=24								
				S-14		2-2-3-3								
						N = 5								
						REC=24								
30	- With Sand		150	S-15		1-2-3-4								30
						N = 5								
						REC=24								
				S-16		1-3-5-7								
						N = 8								
						REC=24								
35	Moist, light brown, loose to medium dense, Silty SAND (SM)		145	S-17		3-8-10-13								
						N = 18								
						REC=24								
				S-18		7-9-12-18								35
						N = 21								
						REC=24								
	- Brown, trace Gravel		140	S-19		4-8-12-16								
						N = 20								
						REC=24								
				S-20		2-6-9-9								
						N = 15								

KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **178.50 (ft)**

TEST BORING LOG

B-11

SHEET **3** OF **3**

Driller: Jerry/Hillis Carnes	Method: HSA	Casing Length: 98.5 ft	Date Begun: 5/13/2014
KCI Representative: SS	Hammer Type: Automatic	Casing Diameter: 3.25	Date Completed: 5/13/2014

Groundwater Levels (feet)

0 hour: Dry
24 hours:

DEPTH (ft)	SOIL CLASSIFICATION AND REMARKS SEE KEY SYMBOL SHEET FOR EXPLANATION OF SYMBOLS AND ABBREVIATIONS BELOW.	LITHOLOGY	ELEV (ft)	IDNET	TYPE	SAMPLES				PLASTIC M.C. LIQUID				
						N-COUNT				I - - - - - I				
						1st 6"	2nd 6"	3rd 6"	4th 6"	□ FINES (%) ● SPT (bpf)				
						REC RQD				20	40	60	80	100
	Moist, reddish brown, stiff to very stiff, Lean CLAY (CL)					REC=18								
85			95	S-29	⊗		6-9-9 N = 18 REC=10			●				85
90			90	S-30	⊗		3-7-9 N = 16 REC=18			●				90
95	Moist, reddish gray, very stiff, Lean CLAY, with Silt seams (CL)		85	S-31	⊗		4-7-9 N = 16 REC=18			●				95
100	Moist, dark gray with reddish gray, very stiff, Lean CLAY, with cemented Clay Nodules (CL)		80	S-32	⊗		4-7-8 N = 15 REC=18			●				100
	Boring terminated at 100 ft. bgs													
	Notes: 1) Water not encountered during drilling. 2) Cave-in occurred at 92 feet bgs after drilling.													
105			75											105
110			70											110
115			65											115
			60											



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **114.34 (ft)**

TEST LOG


B-13

SHEET **1** OF **3**

Driller: **Ron/CenKen** Method: **Mud Rotary** Casing Length: **73.5 ft** Date Begun: **5/8/2014**
 KCI Representative: **SS** Hammer Type: **Automatic** Casing Diameter: **5** Date Completed: **5/8/2014**

Groundwater Levels (feet)

0 hour: _____
 24 hours: _____



KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **114.34 (ft)**

TEST LOG


B-13

SHEET **2** OF **3**

Driller: Ron/CenKen	Method: Mud Rotary	Casing Length: 73.5 ft	Date Begun: 5/8/2014
KCI Representative: SS	Hammer Type: Automatic	Casing Diameter: 5	Date Completed: 5/8/2014

Groundwater Levels (feet)

0 hour: _____
24 hours: _____



KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **114.34 (ft)**

TEST LOG

B-13

SHEET **3** OF **3**

Driller: **Ron/CenKen** Method: **Mud Rotary** Casing Length: **73.5 ft** Date Begun: **5/8/2014**
KCI Representative: **SS** Hammer Type: **Automatic** Casing Diameter: **5** Date Completed: **5/8/2014**

Groundwater Levels (feet)

0 hour: _____

24 hours: _____

DEPTH (ft)	SOIL CLASSIFICATION AND REMARKS SEE KEY SYMBOL SHEET FOR EXPLANATION OF SYMBOLS AND ABBREVIATIONS BELOW.	LITHOLOGY	ELEV (ft)	SAMPLES				PLASTIC M.C. LIQUID						
				IDNET	TYPE	N-COUNT				-----▲-----				
						1st 6"	2nd 6"	3rd 6"	4th 6"	<input type="checkbox"/> FINES (%)				
						REC RQD				<input checked="" type="radio"/> SPT (bpf)				
								20	40	60	80	100		
	2) Groundwater not recorded in borehole due to mud rotary drilling. 3) Inclinometer No. IN-1 installed in borehole to a depth of 74.2 feet.													
85			30										85	
90			25										90	
95			20										95	
100			15										100	
105			10										105	
110			5										110	
115			0										115	
			-5											



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **109.39 (ft)**

TEST BORING LOG

B-14


SHEET **1** OF **2**

Driller: **Ron/CenKen** Method: **HSA** Casing Length: **58.5 ft** Date Begun: **5/7/2014**

KCI Representative: **SS** Hammer Type: **Automatic** Casing Diameter: **3.25** Date Completed: **5/7/2014**

Groundwater Levels (feet)

0 hour: 36
24 hours: 9.8





PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **109.39 (ft)**

TEST BORING LOG

B-14

SHEET **2** OF **2**

Driller: Ron/CenKen	Method: HSA	Casing Length: 58.5 ft	Date Begun: 5/7/2014
KCI Representative: SS	Hammer Type: Automatic	Casing Diameter: 3.25	Date Completed: 5/7/2014

Groundwater Levels (feet)

0 hour: 36
24 hours: 9.8

DEPTH (ft)	SOIL CLASSIFICATION AND REMARKS SEE KEY SYMBOL SHEET FOR EXPLANATION OF SYMBOLS AND ABBREVIATIONS BELOW.	LITHOLOGY	ELEV (ft)	IDNET	TYPE	SAMPLES				PLASTIC M.C. LIQUID				
						N-COUNT				I - - - - - I				
						1st 6"	2nd 6"	3rd 6"	4th 6"	□ FINES (%) ● SPT (bpf)				
	Moist to wet, olive gray, stiff to very stiff, Sandy SILT, with Shells and Mica (ML)													
45	Moist to wet, brown, olive gray, medium dense, Silty SAND with Shells and Mica (SM)		65	S-20			4-7-10 N = 17 REC=18							
50			60	S-21			8-13-16 N = 29 REC=18							
55			55	S-22			7-11-13 N = 24 REC=18							
60			50	S-23			6-9-11 N = 20 REC=18							
	Boring terminated at 60 ft. bgs													
65	Notes: 1) Water encountered in augers at 16.5 feet bgs during drilling and 54.8 feet at completion of drilling; 36 feet bgs after pulling augers; and 9.8 feet bgs 24 hrs after drilling. 2) Cave-in occurred at 48.5 feet after drilling, and 25.5 feet bgs 24 hrs after drilling.		45											
70			40											
			35											
75			30											

KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **107.88 (ft)**

TEST BORING LOG

B-15

SHEET **1** OF **2**

Driller: Ron/CenKen	Method: HSA	Casing Length: 68.5 ft	Date Begun: 5/7/2014
KCI Representative: SS	Hammer Type: Automatic	Casing Diameter: 3.25	Date Completed: 5/7/2014

Groundwater Levels (feet)

0 hour: 59
24 hours: 10.1

DEPTH (ft)	SOIL CLASSIFICATION AND REMARKS SEE KEY SYMBOL SHEET FOR EXPLANATION OF SYMBOLS AND ABBREVIATIONS BELOW.	LITHOLOGY	ELEV (ft)	IDNET	TYPE	SAMPLES				PLASTIC M.C. LIQUID				
						N-COUNT				I - - - - - I				
						1st 6"	2nd 6"	3rd 6"	4th 6"	□ FINES (%) ● SPT (bpf)				
						REC RQD				20 40 60 80 100				
	FILL Sampled As: Moist, dark brown, soft, Sandy SILT, with Gravel (ML)			S-1		2-2-1-2 N = 3 REC=10				●				
	FILL Sampled As: Moist, dark brown, very soft to soft, Sandy CLAY, trace Gravel (CL) - with Wood fragments		105	S-2		1-1-1-2 N = 2 REC=16				●				
5				S-3		2-2-2-3 N = 4 REC=10				●				5
	Moist, dark brown to gray, medium stiff, Sandy Lean CLAY with Sand, trace Gravel (CL)		100	S-4		2-4-3-4 N = 7 REC=23				●				
10				S-5		1-3-2-3 N = 5 REC=18				●				10
	Moist to wet, brown, soft, Sandy SILT, trace Gravel (ML)			S-6		1-1-2-2 N = 3 REC=16				●				
	Moist to wet, gray to reddish brown, soft, Lean CLAY, with Silty SAND Layer (CL)		95	S-7		1-1-2-3 N = 3 REC=24				●				
15				S-8		1-2-3-3 N = 5 REC=20				●				15
	Moist, gray, medium stiff, Lean CLAY (CL)		90											
20				S-9		2-2-4-4 N = 6 REC=24				●				20
	Moist, reddish brown, medium stiff, Lean CLAY (CL) -Vertical cracks at top -Horizontal crack between 23.2'-23.8' -Sand lens		85	ST-1		REC=16								
25				S-10		2-3-3 N = 6 REC=18				●				25
			80											
30				S-11		2-4-7 N = 11 REC=18				●				30
	Moist, gray, stiff, Lean CLAY, with trace Sand (CL)		75											
35				S-12		4-9-9 N = 18 REC=18				●				35
	Moist, dark gray to black, stiff to very stiff, Sandy SILT, with Shell and Mica (ML)		70											

KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **107.88 (ft)**

TEST BORING LOG

B-15

SHEET **2** OF **2**


Driller: **Ron/CenKen** Method: **HSA** Casing Length: **68.5 ft** Date Begun: **5/7/2014**

KCI Representative: **SS** Hammer Type: **Automatic** Casing Diameter: **3.25** Date Completed: **5/7/2014**

Groundwater Levels (feet)

0 hour: 59 ▽

24 hours: 10.1 ▼





PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **83.48 (ft)**

TEST LOG


B-16

SHEET **2** OF **2**

Driller: Ron/CenKen	Method: Mud Rotary	Casing Length: 53 ft	Date Begun: 5/9/2014
KCI Representative: SS	Hammer Type: Automatic	Casing Diameter: 5	Date Completed: 5/9/2014

Groundwater Levels (feet)

0 hour: 5 ▽
24 hours: _____



KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **109.97 (ft)**

TEST LOG


B-17

SHEET **1** OF **2**

Driller: **Ron/CenKen** Method: **Mud Rotary** Casing Length: **69.2 ft** Date Begun: **5/9/2014**
 KCI Representative: **SS** Hammer Type: **Automatic** Casing Diameter: **5** Date Completed: **5/9/2014**

Groundwater Levels (feet)

0 hour: _____
 24 hours: _____



KCI-KOA PLOG PISCATAWAY DRIVE SLOPE FAILURE.GPJ MD SHA REVISED TEMPLATE.GDT 5/19/14



PROJECT **Piscataway Dr. Slope Failures**

PROJECT NO. **07100627W**

Surface Elevation **109.97 (ft)**

TEST LOG

B-17

SHEET **2** OF **2**



Driller: Ron/CenKen	Method: Mud Rotary	Casing Length: 69.2 ft	Date Begun: 5/9/2014
KCI Representative: SS	Hammer Type: Automatic	Casing Diameter: 5	Date Completed: 5/9/2014

Groundwater Levels (feet)

0 hour: _____

24 hours: _____

DEPTH (ft)	SOIL CLASSIFICATION AND REMARKS SEE KEY SYMBOL SHEET FOR EXPLANATION OF SYMBOLS AND ABBREVIATIONS BELOW.	LITHOLOGY	ELEV (ft)	IDNET	TYPE	SAMPLES				PLASTIC M.C. LIQUID				
						N-COUNT				-----▲-----				
						1st 6"	2nd 6"	3rd 6"	4th 6"	□ FINES (%) ● SPT (bpf)				
						REC	RQD			20	40	60	80	100
	Moist, olive gray, stiff to hard, Sandy SILT, with Shells and Mica, with Silty Sand Layers (ML)													
45	Moist, olive gray, Silty SAND with Shells and Mica (SM)		65											45
50			60											50
55			55											55
60			50											60
65			45											65
70	Boring terminated at 69.2 ft. bgs		40											70
75	Note: 1) Lost drilling mud fluid at 7.5 feet and between 25 and 26 feet. 2) Soil samples not taken after 32 and 69.2 feet bgs. 3) Groundwater not recorded in borehole due to mud rotary drilling. 4) Inclinator No. IN-3 installed in borehole to a depth of 69.2 feet.		35											75





HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington, Maryland	Position:		Ground level:	Test no:
Project ID:	S14103	Client:	KCI	Date:	CPT-1
Project:	Fort Washington Slope			5/13/14	Scale:
				1/2	1 : 75
				Page:	Fig:
				File:	
				SLOPE KCI CPT-1.CSV	




HILLIS-CARNES
ENGINEERING ASSOCIATES


Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150





Location:	Fort Washington, Maryland	Position:		Ground level:	Test no:
Project ID:	S14103	Client:	KCI	Date:	CPT-1
Project:	Fort Washington Slope			Page:	Scale:
				2/2	1 : 75
				File:	Fig:
				SLOPE KCI CPT-1.CSV	



HILLIS-CARNES
ENGINEERING ASSOCIATES


 Cone No: NEW2014
 Tip area [cm2]: 10
 Sleeve area [cm2]: 150

Location:	Fort Washington, Maryland	Position:		Ground level:	Test no:
Project ID:	S14103	Client:	KCI	Date:	CPT-1
Project:	Fort Washington Slope			5/13/14	Scale:
				1/2	1 : 75
				Page:	Fig:
				File:	
				SLOPE KCI CPT-1.cpd	





HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-2
Project ID:	S14103	Client:	KCI Technologies	Date:	5/9/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	1/2	Fig:	
				File:	SLOPE KCI CPT-2.CPT		





HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-2
Project ID:	S14103	Client:	KCI Technologies	Date:	5/9/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	2/2	Fig:	
				File:	SLOPE KCI CPT-2.CPT		




HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm²]: 10
Sleeve area [cm²]: 150

Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-3
Project ID:	S14103	Client:	KCI Technologies	Date:	5/9/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	1/2	Fig:	
				File:	SLOPE KCI CPT-3.cpd		



Sandy silt to clayey silt (6)





HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-3
Project ID:	S14103	Client:	KCI Technologies	Date:	5/9/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	2/2	Fig:	
				File:	SLOPE KCI CPT-3.cpd		



HILLIS-CARNES
ENGINEERING ASSOCIATES


Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-4
Project ID:	S14103	Client:	KCI Technologies	Date:	5/9/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	1/2	Fig:	
				File:	SLOPE KCI CPT-4.cpd		



Sandy silt to clayey silt (6)





HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-4
Project ID:	S14103	Client:	KCI Technologies	Date:	5/9/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	2/2	Fig:	
				File:	SLOPE KCI CPT-4.cpd		






HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm²]: 10
Sleeve area [cm²]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-5
Project ID:	S14103	Client:	KCI Technologies	Date:	5/9/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	1/2	Fig:	
				File:	SLOPE KCI CPT-5.cpd		




HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-5
Project ID:	S14103	Client:	KCI Technologies	Date:	5/9/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	2/2	Fig:	
				File:	SLOPE KCI CPT-5.cpd		





HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
 Tip area [cm²]: 10
 Sleeve area [cm²]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-5
Project ID:	S14103	Client:	KCI Technologies	Date:	5/9/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	1/2	Fig:	
				File:	SLOPE KCI CPT-5.CPT		





HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-6
Project ID:	S14103	Client:	KCI Technologies	Date:	5/13/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	1/1	Fig:	
				File:	SLOPE KCI CPT-6.cpd		






HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-7
Project ID:	S14103	Client:	KCI Technologies	Date:	5/13/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	1/2	Fig:	
				File:	SLOPE KCI CPT-7.cpd		





HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-7
Project ID:	S14103	Client:	KCI Technologies	Date:	5/13/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	2/2	Fig:	
				File:	SLOPE KCI CPT-7.cpd		





HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington Slope	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-8
Project ID:	S14103	Client:	KCI Technologies	Date:	5/13/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	1/2	Fig:	
				File:	SLOPE KCI CPT-8.cpd		





HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington Slope	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-8
Project ID:	S14103	Client:	KCI Technologies	Date:	5/13/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	2/2	Fig:	
				File:	SLOPE KCI CPT-8.cpd		





HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm²]: 10
Sleeve area [cm²]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-9
Project ID:	S14103	Client:	KCI Technologies	Date:	5/13/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	1/2	Fig:	
				File:	SLOPE KCI CPT-9.cpd		





HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-9
Project ID:	S14103	Client:	KCI Technologies	Date:	5/13/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	2/2	Fig:	
				File:	SLOPE KCI CPT-9.cpd		




HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150




Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-10
Project ID:	S14103	Client:	KCI Technologies	Date:	5/13/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	1/2	Fig:	
				File:	SLOPE KCI CPT-10.cpd		



Sandy silt to clayey silt (6)

Silty sand to sandy silt (7)

Sandy silt to clayey silt (6)



HILLIS-CARNES
ENGINEERING ASSOCIATES

Cone No: NEW2014
Tip area [cm2]: 10
Sleeve area [cm2]: 150



Location:	Fort Washington, Maryland	Position:	X: 0.00 ft, Y: 0.00 ft	Ground level:	0.00	Test no:	CPT-10
Project ID:	S14103	Client:	KCI Technologies	Date:	5/13/2014	Scale:	1 : 75
Project:	Fort Washington Slope			Page:	2/2	Fig:	
				File:	SLOPE KCI CPT-10.cpd		

FIELD EXPLORATORY PROCEDURES

Standard Penetration Tests

The general field procedures employed by KCI are summarized in ASTM specification D 420 entitled “Investigating and Sampling Soils and Rocks for Engineering Purposes.” This recommended practice lists recognized methods for determining soil and rock distribution and ground water conditions. These methods include geophysical and in-situ borings.

Borings are advanced to obtain subsurface samples using one of several techniques depending upon the site and subsurface conditions. These techniques are:

1. Continuous hollow-stem augers;
2. Wash borings using roller cone or drag bits (mud or water);
3. Continuous flight augers (ASTM D 1452);
4. Continuous sampling using a Tripod-mounted drill rig.

These drilling methods are not capable of penetrating through material designated as “refusal materials.” Refusal may result from hard cemented soil, soft watered rock, coarse gravel or boulders, thin rock seams, or the upper surface of sound continuous rock. Core drilling procedures are required to determine the character and continuity of refusal materials.

The Driller reports the subsurface conditions encountered during drilling on a field test boring record. The record contains information concerning the boring method, samples attempted and recovered, indications of the presence of various materials such as coarse gravel, cobbles, etc., and observation of ground water. It also contains the driller’s interpretation of the soil conditions between samples. Therefore, these boring records contain both factual and interpretive information.

A geotechnical engineer reviews the soils and rock samples plus the field boring records. The engineer classifies the soils in general accordance with the procedures outlined in ASTM Specification D 2488 and prepares the final boring records, which are the basis for all evaluations and recommendations. The final test boring records represent our interpretation of the contents of the field records based on the results of the engineering examination and tests of the field samples. These records depict subsurface conditions at the specific locations and at the particular time when drilled. Soil conditions at other locations may differ from conditions occurring at these boring locations. Also, the passage of time may result in a change in

the subsurface soil and ground water conditions at these boring locations. The lines designating the interface between soil or refusal materials on the records and on profiles represent approximate boundaries. The actual transition between materials may be gradual. The final Test Boring Records are included in Appendix B.

Cone Penetration Test

The standardized cone-penetrometer test (CPT) involves pushing a 1.41-inch diameter 55 to 60 cone through the underlying ground at a rate of 1 to 2 cm/sec. CPT soundings can be very effective in site characterization, especially sites with discrete stratigraphic horizons or discontinuous lenses. Cone penetrometer testing, or CPT (ASTM D-3441), is a valuable method of assessing subsurface stratigraphy associated with soft materials, discontinuous lenses, organic materials (peat), potentially liquefiable materials (silt, sands and granular gravel) and landslides.

Cone rigs can usually penetrate normally consolidated soils and colluvium, but have also been employed to characterize weathered Quaternary and Tertiary-age strata. Cemented or unweathered horizons, such as sandstone, conglomerate or massive volcanic rock can impede advancement of the probe. The cone is able to delineate even the smallest (0.64 mm/1/4-inch thick) low strength horizons, easily missed in conventional (small-diameter) sampling programs.

Most of the commercially-available CPT rigs operate electronic friction cone and piezocone penetrometers, whose testing procedures are outlined in ASTM D-5778. These devices produce a computerized log of tip and sleeve resistance, the ratio between the two, induced pore pressure just behind the cone tip, pore pressure ratio (change in pore pressure divided by measured pressure) and lithologic interpretation of each 2 cm interval are continuously logged and printed out.

Tip Resistance

The tip resistance is measured by load cells located just behind the tapered cone. The tip resistance is theoretically related to undrained shear strength of a saturated cohesive material, while the sleeve friction is theoretically related to the friction of the horizon being penetrated. The tapered cone head forces failure of the soil about 15 inches ahead of the tip and the resistance is measured with an embedded load cell in tons/ft² (tsf).

Local Friction

The local friction is measured by tension load cells embedded in the sleeve for a distance of 4 inches behind the tip. They measure the average skin friction as the probe is advanced through the soil. If cohesive soils are partially saturated, they may exert appreciable skin friction, negating the interpretive program.

Friction ratio

The friction ratio is given in percent. It is the ratio of skin friction divided by the tip resistance (both in tsf). It is used to classify the soil, by its behavior, or reaction to the cone being forced through the soil. High ratios generally indicate clayey materials (high c , low ϕ) while lower ratios are typical of sandy materials (or dry desiccated clays). Typical skin friction to tip friction ratios are 1 % to 10%. The ratio seldom, if ever, exceeds 15%. Sands are generally identified by exhibiting a ratio $< 1\%$.

Pore Pressure

Piezocoones also measure in-situ pore pressure (in psi), in either dynamic (while advancing the cone) or static (holding the cone stationary) modes. Piezocoones employ a porous plastic insert just behind the tapered head that is made of hydrophilic polypropylene, with a nominal particle size of 120 microns (Figure 5). The piezocell must be saturated with glycerin prior to its employment. The filter permeability is about 0.01 cm/sec (1×10^{-2} cm/sec). When using the cone to penetrate dense layers, such as cemented siltstone, sandstone or conglomerate, the piezo filter element can become compressed, thereby inducing high positive pore pressures. But, the plastic filters do not exhibit this tendency, though they do become brittle with time and may need to be replaced periodically. In stiff over-consolidated clays the pore pressure gradient around the cone may be quite high. This pore pressure gradient often results in dissipations recorded behind the CPT tip that initially increase before decreasing to the equilibrium value.

Differential Pore Pressure

The Differential Pore Pressure Ratio is used to aid in soil classification according to the Unified Soil Classification System (USCS). When the cone penetrates dense materials like sand, the sand dilates and the pore pressure drops. In clayey materials high pore pressures may be induced by the driving of the cone head. If transient pore pressures are being recorded that seem non-hydrostatic, most experienced operators will ask that the penetration be halted and allowed at least 5 minutes to equilibrate, so a quasi-static pore pressure reading can be recorded. Sometimes equilibration can take 10 to 30 minutes, depending on the soil. In practice experienced operators try to stop the advance and take pore pressure measurements in recognized aquifers and just above or adjacent to indicated aquacludes.

Piezometer

Water-level readings taken during the field operations do not provide information on the long-term fluctuations of the water table. When this information is required, observation wells/piezometers are necessary to prevent the borings from caving. Observation wells are constructed in accordance to ASTM D5092 by inserting PVC plastic pipe to the desired depths. A closed end slotted portion of PVC pipe is attached to the bottom of the plastic pipe to allow subsurface water to enter the observation well. Clean sand is backfilled around the bottom slotted portion of the well. The remainder of the hole is backfilled with an impervious material, using a bentonite or mortar cap to seal out surface water. The top of the PVC pipe has a removable cover to seal out rainwater.

SLOPE AND WATER-LEVEL MONITORING PROCEDURES

Inclinometer

The general slope monitoring procedures employed by KCI are summarized in ASTM specification D 6230 entitled “Standard Test Method for Monitoring Ground Movement Using Probe-Type Inclinometers”. The apparatus, casing installation procedures, deflection survey procedures, and data reduction method are described in this standard.

The inclinometer casing is a pipe with two sets of grooves running inside the pipe throughout its length. The two sets of grooves are oriented perpendicular to each other, and facilitate inclinometer surveys in mutually perpendicular directions. The pipe may be made up of plastic, aluminum alloy or fiberglass. We used a three inch inside diameter Polyvinyl Chloride (PVC) pipe to perform the deflection survey. The pipe is capped at its bottom end and sealed to prevent the inflow of soil or water. The probe type inclinometer uses sensors inside the probe to indicate the orientation of the probe. The sensors are force balance accelerometers which give voltage outputs proportional to inclination of the probe. A portable readout unit with power supplies for sensors and display records the data. The inclinometer probe and readout unit are connected to each other with a cable having distance markings.

After drilling the borehole, the driller inserts the casing to desired depths. The casings are usually available in 10 feet long pieces and are connected on site. The rubber “O-ring” is sometimes used at connections to seal the joint. The casing is oriented in such a way that one set of grooves aligns with the direction of maximum anticipated movement. This orientation is commonly referred to as A direction. The other set of grooves is referred to as B direction. The driller may add water inside the casing to overcome buoyancy. The annular space between the casing and the borehole is backfilled using cement-sand grout.

For deflection survey, a geotechnical engineer inserts a calibrated inclinometer probe to the bottom of the casing. The probe is aligned in A direction. The engineer makes a measurement traverse by holding the probe stationary at each depth interval and records depth and reading. The reading interval is usually equal to the wheel spacing on the probe. After each reading, the probe is raised by the reading interval and next set of readings taken. The procedure is repeated to the top of the casing to complete the traverse. The probe is then rotated by 180° and the above procedure is repeated. For uniaxial probes, two more traverses are made in B direction in the same way as for the A direction. The deflection surveys may be performed at desired intervals of time depending upon project requirements.

The recorded data are reduced using the software compatible with the probe. Two plots consisting of movements in A and B directions with respect to the elevations are usually drawn to indicate the ground movements. We will provide our slope monitoring results in a separate memorandum within two weeks from our last deflection survey.


Piezometer

Water-level readings taken during the field operations do not provide information on the long-term fluctuations of the water table. When this information is required, observation wells/piezometers are necessary to prevent the borings from caving. Observation wells were constructed in accordance to ASTM D5092 by inserting PVC plastic pipe to the desired depths. A closed end slotted portion of PVC pipe is attached to the bottom of the plastic pipe to allow subsurface water to enter the observation well. Clean sand is backfilled around the bottom slotted portion of the well. The remainder of the hole is backfilled with an impervious material, using a bentonite or mortar cap to seal out surface water. The top of the PVC pipe has a removable cover to seal out rainwater.

LABORATORY TESTING RESULTS

Boring	Depth (ft)	Liquid Limit (%)	Plastic Limit (%)	Plasticity Index (%)	% < #4 Sieve	% < #200 Sieve	Classification	Water Content (%)
B-01	6.0 - 8.0				98	71		28.6
B-01	15.0 - 17.0	43	25	18				27.1
B-01	29.0 - 31.0				100	21		9.7
B-02	2.0 - 4.0							8.4
B-02	12.0 - 14.0				83	29		14.0
B-02	14.0 - 16.0	35	23	12				26.2
B-02	34.0 - 35.5	NP	NP	NP	100	24	SM	20.1
B-03	2.0 - 4.0	29	18	11				18.2
B-03	8.0 - 10.0	39	21	18				27.3
B-03	18.0 - 20.0				100	26		12.4
B-03	30.0 - 32.0				100	31		12.8
B-03	48.5 - 50.0				92	27		30.7
B-04	4.0 - 6.0	42	23	19				27.3
B-04	16.0 - 18.0	59	30	29				36.3
B-04	34.0 - 36.0				100	21		17.1
B-07	8.0 - 10.0	56	28	28				30.5
B-07	18.0 - 20.0	41	24	17				41.4
B-07	30.0 - 32.0				100	33		48.0
B-07	40.0 - 42.0	29	25	4				24.0
B-09	10.0 - 12.0	33	17	16				18.9
B-09	20.0 - 22.0	32	23	9	100	82	CL	34.9
B-09	26.0 - 28.0	35	24	11	100	71	CL	45.0
B-09	34.0 - 36.0	31	21	10				24.4
B-09	53.5 - 55.0	26	23	3	100	45	SM	27.2
B-13	16.0 - 18.0				100	28		28.5
B-13	24.0 - 26.0	39	23	16				34.4
B-13	26.0 - 28.0	51	25	26				34.9

Boring	Depth (ft)	Liquid Limit (%)	Plastic Limit (%)	Plasticity Index (%)	% < #4 Sieve	% < #200 Sieve	Classification	Water Content (%)
B-13	30.0 - 32.0	37	23	14				32.7
B-13	38.0 - 40.0	28	22	6	100	54	CL-ML	26.1
B-16	4.0 - 6.0	54	27	27				31.2
B-16	12.0 - 14.0				100	56		16.2
B-16	22.0 - 24.0				100	26		17.8
B-16	33.0 - 35.0				100	80		23.4
B-17	8.0 - 10.0	NP	NP	NP	100	34	SM	43.7
B-17	16.0 - 18.0	33	25	8				29.0
B-17	30.0 - 32.0	55	25	30				35.3
Shear Plane	0.0 - 0.0	37	27	10	100	77	ML	36.4



	Boring	Depth	LL	PL	PI	Fines	Classification
●	B-01	15.0 - 17.0	43	25	18		Brown CLAY
⊠	B-02	14.0 - 16.0	35	23	12		Brownish gray CLAY
▲	B-02	34.0 - 35.5	NP	NP	NP	24	Gray, silty SAND [SM]
★	B-03	2.0 - 4.0	29	18	11		Brownish gray CLAY
⊙	B-03	8.0 - 10.0	39	21	18		Brown CLAY
⊕	B-04	4.0 - 6.0	42	23	19		Brown to gray CLAY
○	B-04	16.0 - 18.0	59	30	29		Gray fat CLAY
△	B-07	8.0 - 10.0	56	28	28		Brown fat CLAY
⊗	B-07	18.0 - 20.0	41	24	17		Grayish brown CLAY
⊕	B-07	40.0 - 42.0	29	25	4		Dark gray SILT
□	B-09	10.0 - 12.0	33	17	16		Brown, CLAY with little sand
⊗	B-09	20.0 - 22.0	32	23	9	82	Tan, lean CLAY with sand [CL]
⊕	B-09	26.0 - 28.0	35	24	11	71	Light gray, lean CLAY with sand [CL]
☆	B-09	34.0 - 36.0	31	21	10		Brown CLAY
⊗	B-09	53.5 - 55.0	26	23	3	45	Dark gray, silty SAND [SM]
■	B-13	24.0 - 26.0	39	23	16		Brown CLAY
◆	B-13	26.0 - 28.0	51	25	26		Brown, fat CLAY
◇	B-13	30.0 - 32.0	37	23	14		Brown CLAY

Test Method: **ASTM D4318**

Tested By: Ian

Date: 5/11/2014



Beltsville, MD 20705

ATTERBERG LIMITS' RESULTS


Project: Piscataway Drive Slope Stabilization

Location: Fort Washington, MD


Project Number: 14-008



Date: 5/13/2014



Project Number: 14-008




	D10	D30	D60	D100
●				12.5
☒		0.107	0.164	4.76
▲		0.108	0.764	19
★		0.092	0.159	4.76
⊙		0.088	0.148	4.76

Test Method: ASTM D422

Tested By: Ian Date: 5/11/2014

COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

	Boring	S No.	Depth	%Gravel	%Sand	%Silt	%Clay	LL	PI	MC(%)	Classification
●	B-01	3	6.0 - 8.0	2.4	26.9	70.7				28.6	Brown, sandy SILT
☒	B-01	10	29.0 - 31.0	0.0	78.9	21.1				9.7	Gray silty SAND
▲	B-02	6	12.0 - 14.0	17.2	53.7	29.1				14.0	Brown, clayey SAND
★	B-02	10	34.0 - 35.5	0.0	75.7	24.3	NP	NP		20.1	Gray, silty SAND [SM]
⊙	B-03	10	18.0 - 20.0	0.0	73.6	26.4				12.4	Gray silty SAND




	D10	D30	D60	D100
●			0.147	4.76
⊠		0.095	0.22	19
▲		0.101	0.156	9.5
★			0.142	9.5
⊙				4.76

Test Method: ASTM D422

Tested By: Ian Date: 5/13/2014

COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

	Boring	S No.	Depth	%Gravel	%Sand	%Silt	%Clay	LL	PI	MC(%)	Classification
●	B-03	16	30.0 - 32.0	0.0	68.6	31.4				12.8	Gray, silty SAND
⊠	B-03	22	48.5 - 50.0	7.9	64.9	27.2				30.7	Gray silty SAND with organics
▲	B-04	12	34.0 - 36.0	0.1	78.5	21.4				17.1	Gray, silty SAND
★	B-07	16	30.0 - 32.0	0.2	66.7	33.1				48.0	Gray silty SAND
⊙	B-09	10	20.0 - 22.0	0.0	18.3	81.7	32	9		34.9	Tan, lean CLAY with sand [CL]




	D10	D30	D60	D100
●				4.76
⊠			0.11	4.76
▲		0.082	0.181	4.76
★			0.083	4.76
⊙			0.081	4.76

Test Method: ASTM D422

Tested By: Ian Date: 5/11/2014

COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Boring	S No.	Depth	%Gravel	%Sand	%Silt	%Clay	LL	PI	MC(%)	Classification
●	B-09	13	26.0 - 28.0	0.0	29.2	70.8	35	11	45.0	Light gray, lean CLAY with sand [CL]
⊠	B-09	24	53.5 - 55.0	0.0	54.7	45.3	26	3	27.2	Dark gray, silty SAND [SM]
▲	B-13	9	16.0 - 18.0	0.0	71.7	28.3			28.5	Gray silty SAND
★	B-13	19	38.0 - 40.0	0.0	45.5	54.5	28	6	26.1	Dark gray, sandy silty CLAY [CL-ML]
⊙	B-16	7	12.0 - 14.0	0.0	43.7	56.3			16.2	Brownish gray, sandy SILT



	D10	D30	D60	D100
●		0.083	0.148	4.76
◻				9.5
▲			0.117	4.76
★				9.5

Test Method: ASTM D422

Tested By: Ian Date: 5/13/2014

COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

	Boring	S No.	Depth	%Gravel	%Sand	%Silt	%Clay	LL	PI	MC(%)	Classification
●	B-16	12	22.0 - 24.0	0.0	74.0	26.0				17.8	Gray, silty SAND
◻	B-16	16	33.0 - 35.0	0.2	20.0	79.8				23.4	Gray, sandy SILT
▲	B-17	5	8.0 - 10.0	0.0	65.7	34.3	NP	NP		43.7	Brown, silty SAND [SM]
★	Shear Plane	Bag	0.0 - 0.0	0.2	22.4	77.4	37	10		36.4	Gray, SILT with sand [ML]



The Robert B. Balter Company
Geotechnical and Environmental Engineers
Materials and Construction Inspection and Testing
Telephone No. (410) 363-1555
www.balterco.com

GRAIN SIZE DISTRIBUTION

TEST METHOD ASTM D422


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER _____

DATE TESTED _____



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Specimen Identification		Classification					LL	PL	PI	Cc	Cu
● B-14, ST-1 @ 26.5' - 28.5',		Reddish Brown (4/4) LEAN CLAY(CL)					38	22	16		
Specimen Identification		D100	D60	D30	D10	%Gravel	%Sand	%Silt		%Clay	
● B-14, ST-1 @ 26.5' - 28.5',		2				0.0	0.2	99.8			


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures




PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER

DATE TESTED

[illegible]

DIRECT SHEAR TEST REPORT



Symbol	⊙	Δ	□	
Test No.	1	2	3	
Sample No.	ST-1	ST-1	ST-1	
Shape	Circular	Circular	Circular	
Initial	Dimension, in	2.5	2.5	2.5
	Area, in ²	4.9087	4.9087	4.9087
	Height, in	1	1	1
	Water Content, %	27.16	31.63	27.33
	Dry Density, pcf	95.567	91.019	97.189
	Saturation, %	92.93	97.37	97.16
	Void Ratio	0.80947	0.89988	0.77927
Consol. Height, in		0.96025	0.97948	0.94706
Consol. Void Ratio		0.73755	0.8609	0.68508
Final	Water Content, %	28.09	33.48	26.87
	Dry Density, pcf	100.54	93.308	104.26
	Saturation, %	108.06	108.70	113.01
	Void Ratio	0.72003	0.85327	0.65865
Normal Stress, psf		1996.6	999.8	3996.2
Max. Shear Stress, psf		1371.3	761.14	1593.8
Ult. Shear Stress, psf		1371.3	618.12	1531.8
Time to Failure, min		27.331	6.0034	14.003
Disp. Rate, in/min		0.01	0.01	0.01
Estimated Specific Gravity		2.77	2.77	2.77
Liquid Limit		38	38	38
Plastic Limit		22	22	22
Plasticity Index		16	16	16

Project: Piscataway Slope Failure

Location: Ft. Washington, MD

Project No.: 16570-0

Boring No.: B-14

Sample Type: Undisturbed

Description: Reddish Brown (4/4) LEAN CLAY(CL)

Remarks: Sample Location: 16570-0 Piscataway Dr. Slope & Road Failures B-14 / ST-1 26.5 - 28.5 - 1.0 TSF



The Robert B. Balter Company
Geotechnical and Environmental Engineers
Materials and Construction Inspection and Testing
Telephone No. (410) 363-1555
www.balterco.com

GRAIN SIZE DISTRIBUTION

TEST METHOD ASTM D422


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER _____

DATE TESTED _____



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Specimen Identification		Classification				LL	PL	PI	Cc	Cu
● B-15, ST-1 @ 22.0' - 24.0',		Yellowish Red (4/6) LEAN CLAY(CL)				40	24	16		
Specimen Identification		D100	D60	D30	D10	%Gravel	%Sand	%Silt	%Clay	
● B-15, ST-1 @ 22.0' - 24.0',		9.5				3.1	7.3	89.7		


GRAIN SIZE 16570-0 PISCATAWAY SLOPE FAILURE.GPJ MTA REDLINE.GDT 5/20/14

CLIENT KCI Technologies




PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER _____ DATE TESTED _____



[illegible]

DIRECT SHEAR TEST REPORT



Symbol	○	△	□	
Test No.	1	2	3	
Sample No.	ST-1	ST-1	ST-1	
Shape	Circular	Circular	Circular	
Initial	Dimension, in	2.5	2.5	2.5
	Area, in ²	4.9087	4.9087	4.9087
	Height, in	1	1	1
	Water Content, %	34.73	31.78	27.92
	Dry Density, pcf	86.859	93.014	96.304
	Saturation, %	97.09	102.47	97.22
	Void Ratio	0.99087	0.85914	0.79562
Consol. Height, in		0.97489	0.95793	0.94724
Consol. Void Ratio		0.94088	0.78093	0.70089
Final	Water Content, %	36.22	31.04	26.93
	Dry Density, pcf	90.207	98.626	104.16
	Saturation, %	109.42	114.13	112.99
	Void Ratio	0.91698	0.75334	0.66026
Normal Stress, psf		896.27	1798.5	3595.4
Max. Shear Stress, psf		772.26	754.78	2280.2
Ult. Shear Stress, psf		503.72	754.78	2175.4
Time to Failure, min		8.0034	27.152	12.003
Disp. Rate, in/min		0.01	0.01	0.01
Estimated Specific Gravity		2.77	2.77	2.77
Liquid Limit		40	40	40
Plastic Limit		24	24	24
Plasticity Index		16	16	16
Project: Piscataway Slope Failure				
Location: Ft. Washington, MD				
Project No.: 16570-0				
Boring No.: B-15				
Sample Type: Undisturbed				
Description: Yellowish Red (4/6) LEAN CLAY(CL)				
Remarks: Sample Location: 16570-0 Piscataway Dr. Slope & Road Failures B-15 / ST-1 22.0 - 24.0 - 0.45 TSF				

CONSOLIDATED UNDRAINED TRIAXIAL TEST by ASTM D4767



Symbol	⊙	△		
Sample No.	ST-1	ST-1		
Test No.	1	2		
Depth	22'8"-23'2" 23'2"-23'8"			
Initial	Diameter, in	2.82	2.867	
	Height, in	5.57	5.775	
	Water Content, %	33.1	32.8	
	Dry Density, pcf	90.73	89.26	
	Saturation, %	104.3	99.6	
Before Shear	Void Ratio	0.858	0.888	
	Water Content, %	34.4	33.0	
	Dry Density, pcf	87.4	89.09	
	Saturation*, %	100.0	100.0	
	Void Ratio	0.929	0.892	
	Back Press., psi	54.	83.98	
	Ver. Eff. Cons. Stress, psi	10.35	20.84	
	Shear Strength, psi	4.082	7.462	
	Strain at Failure, %	9	4.49	
	Strain Rate, %/min	0.03	0.03	
	B-Value	0.95	0.95	
	Estimated Specific Gravity	2.7	2.7	
	Liquid Limit	40	40	
	Plastic Limit	24	24	

	Project: Piscataway Slope Failure				
	Location: Ft. Washington, MD				
	Project No.: 16570-0				
	Boring No.: B-15				
	Sample Type: Undisturbed				
	Description: Color: Yellowish Red (4/6) LEAN CLAY(CL)				
	Remarks: Sample Location: 16570-0 Piscataway Dr. Slope & Road Failure B-15 / ST-1 - 22.0' - 24.0' 0.7'				

Phase calculations based on start of test.


* Saturation is set to 100% for phase calculations.

CLIENT KCI Technologies




PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER _____ DATE TESTED _____

[illegible]



DIRECT SHEAR TEST REPORT



Symbol	○	△	□	
Test No.	1	2	3	
Sample No.	ST-1	ST-1	ST-1	
Shape	Circular	Circular	Circular	
Initial	Dimension, in	2.5	2.5	2.5
	Area, in ²	4.9087	4.9087	4.9087
	Height, in	1	1	1
	Water Content, %	36.55	35.18	35.28
	Dry Density, pcf	84.415	85.765	84.725
	Saturation, %	96.54	95.89	93.86
	Void Ratio	1.0485	1.0163	1.041
Consol. Height, in		0.97957	0.96906	0.95582
Consol. Void Ratio		1.0067	0.95389	0.95085
Final	Water Content, %	37.23	36.20	36.07
	Dry Density, pcf	85.539	88.581	89.946
	Saturation, %	100.96	105.33	108.31
	Void Ratio	1.0216	0.95216	0.92255
Normal Stress, psf		1002.8	2001.1	3996.2
Max. Shear Stress, psf		1542.9	2146.8	3232
Ult. Shear Stress, psf		932.75	1536.6	2652.1
Time to Failure, min		6.0034	6.0035	8.0033
Disp. Rate, in/min		0.01	0.01	0.01
Estimated Specific Gravity		2.77	2.77	2.77
Liquid Limit		48	48	48
Plastic Limit		30	30	30
Plasticity Index		18	18	18
Description: Very Dark Grayish Brown (3/2) SILT with SAND(ML)				
Remarks: Sample Location: 16570-0 Piscataway Dr. Slope & Road Failures B-13/ ST-1 22.0' - 24.0' - 0.50 TSF				

CONSOLIDATION TEST DATA


SUMMARY REPORT



	Project: Piscataway Slope Failure	Location: Ft. Washington, MD	Project No.: 16570-0
	Boring No.: B-13	Tested By: Jason	Checked By: Jeremy
	Sample No.: ST-1	Test Date: 05/12/2014	Depth: 22'6"-22'7"
	Test No.: 1	Sample Type: Undisturbed	Elevation:
	Description: Color: Very Dark Grayish Brown (3/2) SILT with SAND(ML)		
	Remarks: ASTM D2435. Location: B-13 / ST-1 (22.0' - 24.0') 64 TSF		

CONSOLIDATION TEST DATA

SUMMARY REPORT



				Before Test	After Test	
Overburden Pressure: 1.21 tsf			Water Content, %	34.08	23.01	
Preconsolidation Pressure: 5.5 tsf			Dry Unit Weight, pcf	80.31	104.7	
Compression Index: 0.48			Saturation, %	81.78	97.59	
Diameter: 2 in		Height: 1 in		Void Ratio	1.16	0.65
LL: 48	PL: 30	PI: 18	GS: 2.77			

	Project: Piscataway Slope Failure	Location: Ft. Washington, MD	Project No.: 16570-0
	Boring No.: B-13	Tested By: Jason	Checked By: Jeremy
	Sample No.: ST-1	Test Date: 05/12/2014	Depth: 22'6"-22'7"
	Test No.: 1	Sample Type: Undisturbed	Elevation:
	Description: Color: Very Dark Grayish Brown (3/2) SILT with SAND(ML)		
	Remarks: ASTM D2435. Location: B-13 / ST-1 (22.0' - 24.0') 64 TSF		



The Robert B. Balter Company
Geotechnical and Environmental Engineers
Materials and Construction Inspection and Testing
Telephone No. (410) 363-1555
www.balterco.com

GRAIN SIZE DISTRIBUTION

TEST METHOD ASTM D422


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER _____

DATE TESTED _____



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Specimen Identification		Classification					LL	PL	PI	Cc	Cu
● B-13, ST-2 @ 28.0' - 30.0',		Weak Red (4/4) LEAN CLAY(CL)					39	25	14		
Specimen Identification		D100	D60	D30	D10	%Gravel	%Sand	%Silt		%Clay	
● B-13, ST-2 @ 28.0' - 30.0',		2				0.0	0.5	99.5			


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures




PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER

DATE TESTED

[illegible]

DIRECT SHEAR TEST REPORT



Symbol	⊙	Δ	⊠	
Test No.	1	2	3	
Sample No.	ST-2	ST-2	ST-2	
Shape	Circular	Circular	Circular	
Initial	Dimension, in	2.5	2.5	2.5
	Area, in ²	4.9087	4.9087	4.9087
	Height, in	1	1	1
	Water Content, %	31.82	30.48	31.46
	Dry Density, pcf	89.467	91.741	89.288
	Saturation, %	94.48	95.41	93.05
	Void Ratio	0.93284	0.88494	0.93671
Consol. Height, in		0.97823	0.96713	0.93517
Consol. Void Ratio		0.89077	0.82298	0.81116
Final	Water Content, %	34.10	32.01	31.10
	Dry Density, pcf	92.082	95.882	97.831
	Saturation, %	107.59	110.35	112.23
	Void Ratio	0.87794	0.80352	0.76759
Normal Stress, psf		1097.4	2197.8	4392.6
Max. Shear Stress, psf		873.96	1457.1	2259.6
Ult. Shear Stress, psf		688.04	1082.1	1860.7
Time to Failure, min		10.003	8.0033	14.003
Disp. Rate, in/min		0.01	0.01	0.01
Estimated Specific Gravity		2.77	2.77	2.77
Liquid Limit		39	39	39
Plastic Limit		25	25	25
Plasticity Index		14	14	14
Project: Piscataway Slope Failure				
Location: Ft. Washington, MD				
Project No.: 16570-0				
Boring No.: B-13				
Sample Type: Undisturbed				
Description: Dark Reddish Brown				
Remarks: Sample Location: 16570-0 Piscataway Dr. Slope & Road Failures B-13/ ST-2 28.0' - 30.0' - 0.55 TSF				



The Robert B. Balter Company
Geotechnical and Environmental Engineers
Materials and Construction Inspection and Testing
Telephone No. (410) 363-1555
www.balterco.com

GRAIN SIZE DISTRIBUTION

TEST METHOD ASTM D422


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER _____

DATE TESTED _____




COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Specimen Identification		Classification					LL	PL	PI	Cc	Cu
● B-13, S-2 @ 2.0' - 4.0'		Strong Brown (5/8) LEAN CLAY with SAND(CL)					35	17	18		
Specimen Identification		D100	D60	D30	D10	%Gravel	%Sand	%Silt		%Clay	
● B-13, S-2 @ 2.0' - 4.0'		9.5				1.3	25.7	73.0			

GRAIN SIZE 16570-0 PISCATAWAY SLOPE FAILURE.GPJ MTA REDLINE GDT 5/20/14



CLIENT KCI Technologies PROJECT NAME Piscataway Dr. Slope & Road Failures
PROJECT LOCATION Fort Washington, MD PROJECT NUMBER _____ DATE TESTED _____

[illegible]



The Robert B. Balter Company
Geotechnical and Environmental Engineers
Materials and Construction Inspection and Testing
Telephone No. (410) 363-1555
www.balterco.com

GRAIN SIZE DISTRIBUTION

TEST METHOD ASTM D422


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER

DATE TESTED



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Specimen Identification		Classification					LL	PL	PI	Cc	Cu
● B-13, S-6 @ 10.0' - 12.0',		Pale Brown (6/3) SILTY SAND(SM)					NP	NP	NP		
Specimen Identification		D100	D60	D30	D10	%Gravel	%Sand	%Silt		%Clay	
● B-13, S-6 @ 10.0' - 12.0',		4.75	0.269	0.098		0.0	76.0	24.0			

GRAIN SIZE 16570-0 PISCATAWAY SLOPE FAILURE.GPJ MTA REDLINE.GDT 5/20/14


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER

DATE TESTED

[illegible]



The Robert B. Balter Company
Geotechnical and Environmental Engineers
Materials and Construction Inspection and Testing
Telephone No. (410) 363-1555
www.balterco.com

GRAIN SIZE DISTRIBUTION

TEST METHOD ASTM D422


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER _____

DATE TESTED _____



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Specimen Identification		Classification					LL	PL	PI	Cc	Cu
● B-14, S-5 @ 8.0' - 10.0',		Reddish Yellow (6/8) CLAYEY GRAVEL with SAND(GC)					34	15	19		
Specimen Identification		D100	D60	D30	D10	%Gravel	%Sand	%Silt		%Clay	
● B-14, S-5 @ 8.0' - 10.0',		25	3.186			36.1	30.4	33.6			

GRAIN SIZE 16570-0 PISCATAWAY SLOPE FAILURE.GPJ MTA REDLINE.GDT 5/20/14



The Robert B. Balter Company
Geotechnical and Environmental Engineers
Materials and Construction Inspection and Testing
Telephone No. (410) 363-1555
www.balterco.com

GRAIN SIZE DISTRIBUTION

TEST METHOD ASTM D422


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER

DATE TESTED



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Specimen Identification		Classification					LL	PL	PI	Cc	Cu
● B-14, S-10 @ 19.0' - 21.0',		Light Olive Brown (5/3) CLAYEY SAND(SC)					35	20	15		
Specimen Identification		D100	D60	D30	D10	%Gravel	%Sand	%Silt		%Clay	
● B-14, S-10 @ 19.0' - 21.0',		4.75	0.186	0.082		0.0	72.5	27.5			


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER

DATE TESTED

[illegible]


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER

DATE TESTED



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

[illegible]

GRAIN SIZE 16570-0 PISCATAWAY SLOPE FAILURE.GPJ MTA REDLINE.GDT 5/20/14




The Robert B. Balter Company
Geotechnical and Environmental Engineers
Materials and Construction Inspection and Testing
Telephone No. (410) 363-1555
www.balterco.com

GRAIN SIZE DISTRIBUTION

TEST METHOD ASTM D422

CLIENT KCI Technologies PROJECT NAME Piscataway Dr. Slope & Road Failures
PROJECT LOCATION Fort Washington, MD PROJECT NUMBER _____ DATE TESTED _____



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Specimen Identification		Classification					LL	PL	PI	Cc	Cu
● B-15, S-6 @ 10.0' - 12.0',		Strong Brown (4/6) CLAYEY SAND(SC)					38	22	16		
Specimen Identification		D100	D60	D30	D10	%Gravel	%Sand	%Silt		%Clay	
● B-15, S-6 @ 10.0' - 12.0',		12.5	0.247	0.095		12.3	64.5	23.3			


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER

DATE TESTED

[illegible]



The Robert B. Balter Company
Geotechnical and Environmental Engineers
Materials and Construction Inspection and Testing
Telephone No. (410) 363-1555
www.balterco.com

GRAIN SIZE DISTRIBUTION

TEST METHOD ASTM D422


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER _____

DATE TESTED _____




CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER

DATE TESTED

[illegible]



The Robert B. Balter Company
Geotechnical and Environmental Engineers
Materials and Construction Inspection and Testing
Telephone No. (410) 363-1555
www.balterco.com

GRAIN SIZE DISTRIBUTION

TEST METHOD ASTM D422


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures

PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER

DATE TESTED



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Specimen Identification		Classification					LL	PL	PI	Cc	Cu
●	B-17, ST-1 @ 22.0' - 24.0',	Mottled Greenish Gray / Dark Reddish Brown (2.5/4) LEAN CLAY with					47	19	28		
		SAND(CL)									
Specimen Identification		D100	D60	D30	D10	%Gravel	%Sand	%Silt	%Clay		
●	B-17, ST-1 @ 22.0' - 24.0',	4.75				0.0	25.6	74.4			

GRAIN SIZE 16570-0 PISCATAWAY SLOPE FAILURE.GPJ MTA REDLINE.GDT 5/20/14


CLIENT KCI Technologies

PROJECT NAME Piscataway Dr. Slope & Road Failures




PROJECT LOCATION Fort Washington, MD

PROJECT NUMBER

DATE TESTED

[illegible]

DIRECT SHEAR TEST REPORT



Symbol	⊙	Δ	□	
Test No.	1	2	3	
Sample No.	ST-1	ST-1	ST-1	
Shape	Circular	Circular	Circular	
Initial	Dimension, in	2.5	2.5	2.5
	Area, in ²	4.9087	4.9087	4.9087
	Height, in	1	1	1
	Water Content, %	44.11	47.97	59.94
	Dry Density, pcf	80.619	77.406	71.485
	Saturation, %	106.71	107.69	117.00
	Void Ratio	1.145	1.234	1.419
Consol. Height, in		0.97372	0.95915	0.9382
Consol. Void Ratio		1.0886	1.1427	1.2696
Final	Water Content, %	34.59	33.47	31.27
	Dry Density, pcf	91.104	95.037	99.625
	Saturation, %	106.68	113.11	117.71
	Void Ratio	0.89811	0.81957	0.73576
Normal Stress, psf		1001.3	1996.6	3993.3
Max. Shear Stress, psf		1239.4	2037.1	2995.3
Ult. Shear Stress, psf		730.94	1379.3	2571
Time to Failure, min		10.003	10.003	23.931
Disp. Rate, in/min		0.01	0.01	0.01
Estimated Specific Gravity		2.77	2.77	2.77
Liquid Limit		47	47	47
Plastic Limit		19	19	19
Plasticity Index		28	28	28

Project: Piscataway Slope Failure	
Location: Ft. Washington, MD	
Project No.: 16570-0	
Boring No.: B-17	
Sample Type: Undisturbed	
Description: Dark Brownish Gray	
Remarks: Sample Location: 16570-0 Piscataway Dr. Slope & Road Failures B-17/ ST-1 22.0' - 24.0' - 0.5 TSF (Residual Shear	

LABORATORY TESTING

Natural Moisture Content

The natural moisture content of selected samples was determined in accordance with ASTM D 2216. The moisture content of the soil is the ratio, expressed as a percentage, of the weight of water in a given mass of soil to the weight of the soil particles. The results are summarized in the table following this section of the report.

Grain Size Distribution

Grain size tests were performed on representative soil samples. The samples were washed over a U. S. standard No. 200 sieve to remove the fines (particles finer than a No. 200 mesh sieve). The samples were then dried and sieved through a standard set of nested sieves. This test was performed in a manner similar to that described by ASTM D 1140. The results are presented as percent finer by weight versus particle size curves on the attached Grain Size Distribution sheets.

Soil Plasticity

Representative samples of the site soils were selected for Atterberg Limits testing to determine their soil plasticity characteristics. The soil's Plasticity Index (PI) is representative of this characteristic and is bracketed by the Liquid Limit (LL) and the Plastic Limit (PL). These characteristics are determined in accordance with ASTM D 4318. The LL is the moisture content at which the soil will flow as a heavy viscous fluid. The PL is the moisture content at which the soil begins to lose its plasticity. The data obtained are presented on the attached Grain Size Distribution sheets and summarized in the table following this section of the report.

Certain soils swell and shrink with increases and decreases in soil moisture. The PI is related to this potential volume change ability. When such volume changes occur in soils confined beneath foundations, floor slabs and pavements, structural deformations can be produced. Past experience has shown that soils having a PI of less than 30 are only slightly susceptible to volume changes. Soils having a PI greater than 50 are generally very susceptible to this volume changes. Soils with a PI between these limits have moderate volume change potential. The soils tested at this site are moderately susceptible to volume change.

Percent Fines

The percentage of fine-grained particles present in selected samples was determined by passing the samples through a No. 200 mesh sieve. The percent by weight passing the sieve is the percentage of fines or portion of the sample in the silt and clay size range. This test was conducted in accordance with ASTM D 1140. The results are shown on the attached Grain Size Distribution sheets.

Direct Shear (DS) Test

The consolidated drained strength properties of the selected samples were determined in general accordance with ASTM 3080. The results of the Modified Procter test were utilized in compacting the test samples to the desired density and moisture content for the Direct Shear test. The test method is generally performed in following steps:

1. Place the test specimen in the direct shear device.
2. Apply a predetermined stress, providing for wetting or draining of the test specimen.
3. Consolidate the specimen under normal stress.
4. Unlock the frames that hold the specimen.
5. Displace one frame horizontally with respect to the other at a constant rate of shearing deformation and measure the shearing force and horizontal displacements as the specimen is sheared.
6. Plot the shear stress at failure as a function of normal stress termed as “Mohr-Coulomb diagram”.

A series of such tests at different normal stresses are performed and Mohr-Coulomb diagrams drawn. A failure envelope is drawn with the help of these diagrams and effective stress shearing strength parameters, cohesion (c') and internal friction angle (ϕ') determined. The results of direct shear tests are summarized in the table following this section.


Triaxial Shear

Undisturbed samples are extruded from their sampling tubes for triaxial shear testing. The sections are then trimmed into cylinders 2.4 inches in diameter and encased in rubber membranes. Each is then placed in a compression chamber and confined by all-around water pressure. An increasing axial load is then applied until the sample failed in shear. The test results are presented in the form of Stress-Strain Curves and Mohr Diagrams on the accompanying Triaxial Shear Test sheets.

Consolidation

A single section of the undisturbed sample is extruded from its sampling tube for consolidation testing. The sample is then trimmed into a disc 2.4 inches in diameter and 1-inch thick. The disc is confined in a stainless steel ring and sandwiched between porous plates. It is then subjected to incrementally increasing vertical loads and the resulting deformations measured with a micrometer dial gauge. The test results are presented in the form of a pressure versus percent strain curve on the accompanying consolidation test sheet.

SLOPE STABILITY ANALYSES




Project Mgr: KOA
 Prepared by: SS
 Checked by: KA
 Approved by: KOA

Project No. 07100627.W
 Scale: n/a
 Date: 5/19/2014

KCI TECHNOLOGIES
 ENGINEERS | PLANNERS | SCIENTISTS | CONSTRUCTION MANAGERS
 936 RIDGEBROOK ROAD SPARKS, MD
 PH: (410) 316-7800 Fax: (410) 316-7935

SLOPE STABILITY BACK CALCULATION- CASE A
PISCATAWAY DRIVE SLOPE FAILURE
PRINCE GEORGE'S COUNTY, MARYLAND

FIGURE
D-1



Project Mgr: KOA

Prepared by: SS

Checked by: KA

Approved by: KOA

Project No. 07100627.W

Scale: n/a

Date: 5/19/2014


KCI TECHNOLOGIES
ENGINEERS | PLANNERS | SCIENTISTS | CONSTRUCTION MANAGERS

936 RIDGEBROOK ROAD SPARKS, MD
PH: (410) 316-7800 Fax: (410) 316-7935

SLOPE STABILITY BACK CALCULATION- CASE B

**PISCATAWAY DRIVE SLOPE FAILURE
PRINCE GEORGE'S COUNTY, MARYLAND**

**FIGURE
D-2**




Project Mgr: KOA
 Prepared by: SS
 Checked by: KA
 Approved by: KOA


Project No. 07100627.W
 Scale: n/a
 Date: 5/19/2014

KCI TECHNOLOGIES
 ENGINEERS | PLANNERS | SCIENTISTS | CONSTRUCTION MANAGERS
 936 RIDGEBROOK ROAD SPARKS, MD
 PH: (410) 316-7800 FAX: (410) 316-7935

SLOPE STABILITY BACK CALCULATION- CASE C
PISCATAWAY DRIVE SLOPE FAILURE
PRINCE GEORGE'S COUNTY, MARYLAND

FIGURE
D-3






Project Mgr: KOA
 Prepared by: SS
 Checked by: KA
 Approved by: KOA

Project No. 07100627.W
 Scale: n/a
 Date: 5/19/2014

KCI TECHNOLOGIES
 ENGINEERS | PLANNERS | SCIENTISTS | CONSTRUCTION MANAGERS
 936 RIDGEBROOK ROAD SPARKS, MD
 PH: (410) 316-7800 FAX: (410) 316-7935

SLOPE STABILITY BACK CALCULATION- CASE E
PISCATAWAY DRIVE SLOPE FAILURE
PRINCE GEORGE'S COUNTY, MARYLAND

FIGURE
D-5




Project Mgr: KOA
 Prepared by: SS
 Checked by: KA
 Approved by: KOA

Project No. 07100627.W
 Scale: n/a
 Date: 5/19/2014


KCI TECHNOLOGIES
 ENGINEERS | PLANNERS | SCIENTISTS | CONSTRUCTION MANAGERS
 936 RIDGEBROOK ROAD SPARKS, MD
 PH: (410) 316-7800 Fax: (410) 316-7935


SLOPE STABILITY BACK CALCULATION- CASE F
PISCATAWAY DRIVE SLOPE FAILURE
PRINCE GEORGE'S COUNTY, MARYLAND

FIGURE
D-6



Project Mgr:	KOA	Project No.	07100627.W	KCI TECHNOLOGIES ENGINEERS PLANNERS SCIENTISTS CONSTRUCTION MANAGERS 936 RIDGEBROOK ROAD SPARKS, MD PH: (410) 316-7800 Fax: (410) 316-7935	SLOPE STABILITY BACK CALCULATION- CASE G	FIGURE D-7
Prepared by:	SS	Scale:	n/a			
Checked by:	KA	Date:	5/19/2014		PISCATAWAY DRIVE SLOPE FAILURE PRINCE GEORGE'S COUNTY, MARYLAND	
Approved by:	KOA					






Project Mgr: RSE
 Prepared by: SS
 Checked by: KJS
 Approved by: KJS

Project No. 07100627.W
 Scale: n/a
 Date: 5/19/2014

KCI TECHNOLOGIES
 ENGINEERS | PLANNERS | SCIENTISTS | CONSTRUCTION MANAGERS
 936 RIDGEBROOK ROAD SPARKS, MD
 PH: (410) 316-7800 Fax: (410) 316-7935

SLOPE STABILIZATION- OPTION 1
PISCATAWAY DRIVE SLOPE FAILURE
PRINCE GEORGE'S COUNTY, MARYLAND

FIGURE
D-9




Project Mgr: KOA
 Prepared by: SS
 Checked by: KA
 Approved by: KOA

Project No. 07100627.W
 Scale: n/a
 Date: 5/19/2014

KCI TECHNOLOGIES
 ENGINEERS | PLANNERS | SCIENTISTS | CONSTRUCTION MANAGERS
 936 RIDGEBROOK ROAD SPARKS, MD
 PH: (410) 316-7800 Fax: (410) 316-7935

SLOPE STABILIZATION- OPTION 2
PISCATAWAY DRIVE SLOPE FAILURE
PRINCE GEORGE'S COUNTY, MARYLAND

FIGURE
D-10



Project Mgr: KOA
 Prepared by: SS
 Checked by: KA
 Approved by: KOA


Project No. 07100627.W
 Scale: n/a
 Date: 5/19/2014

KCI TECHNOLOGIES
 ENGINEERS | PLANNERS | SCIENTISTS | CONSTRUCTION MANAGERS
 936 RIDGEBROOK ROAD SPARKS, MD
 PH: (410) 316-7800 Fax: (410) 316-7935

SLOPE STABILIZATION- OPTION 3
PISCATAWAY DRIVE SLOPE FAILURE
PRINCE GEORGE'S COUNTY, MARYLAND

FIGURE
D-11

SLIDE FEATURES



EXISTING SITE CONTOURS

PISCATAWAY DRIVE SLOPE FAILURE

FORT WASHINGTON, PRINCE GEORGES COUNTY, MARYLAND

Figure No.

E-1

ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS

936 Ridgebrook Rd.
Sparks, MD 21152
410-316-7800 | Fax 410-316-7817

DRAWN BY
LSG


APPROVED BY
KA


SCALE
NTS

DATE
MAY 2014

KCI JOB NUMBER
07100627.W







USCS SOIL KEY

	GW		SW		ML		OL
	GP		SP		MH		OH
	GM		SM		CL		FILL
	GC		SC		CH		SANDSTONE

Title:


Piscataway Dr. Slope Failures

Drawn:	Approved:	Date: 5/18/14
---------------	------------------	----------------------

Figure No.

KCI Job No. 07100627W


Monday, May 19, 2014 AT 09:41 AM
M:\2010\07100627.W\Drawings\Roadway\pHC-X001_piscataway.dgn



KCI TECHNOLOGIES
ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS
936 RIDGEBROOK ROAD
SPARKS, MARYLAND 21152
TELEPHONE: (410) 316-7800
FAX: (410) 316-7818

DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION PRINCE GEORGE'S COUNTY, MARYLAND		SCALE: 1"=10'		DWG. 1 OF 6	
PISCATAWAY DRIVE		APPROVED		FOR DARRELL B. MORLEY, DIRECTOR	
CROSS SECTIONS		DESIGNED: DKH		CONTRACT NO. XXX-XXX	
CS-1		DRAWN: BBB		ROAD NO.	
		CHECKED: KTB		JOB NO.	
		APPROVED:		FILE NO.	
		CHIEF, DIV. OF HIGHWAYS & BRIDGES		DATE	

Monday, May 19, 2014 AT 09:41 AM
M:\2010\07100627.W\Drawings\Roadway\pHC-X001_piscataway.dgn



KCI TECHNOLOGIES


ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS

936 RIDGEBROOK ROAD
SPARKS, MARYLAND 21152
TELEPHONE: (410) 316-7800
FAX: (410) 316-7818

DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION PRINCE GEORGE'S COUNTY, MARYLAND		SCALE: 1"=10'		DWG. 2 OF 6	
PISCATAWAY DRIVE		APPROVED		FOR DARRELL B. MORLEY, DIRECTOR	
CROSS SECTIONS		DESIGNED: DKH		CONTRACT NO. XXX-XXX	
CS-2		DRAWN: BBB		ROAD NO. JOB NO.	
		CHECKED: KTB		FILE NO.	
		APPROVED:			
		CHEF, DIV. OF HIGHWAYS & BRIDGES		DATE	

PLOTTED: Monday, May 19, 2014 AT 09:41 AM
FILE: M:\2010\07100627.W\Drawings\Roadway\pHC-X001_piscataway.dgn

Monday, May 19, 2014 AT 09:41 AM
M:\2010\07100627.W\Drawings\Roadway\pHC-X001_piscataway.dgn






KCI
TECHNOLOGIES

ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS

936 RIDGEBROOK ROAD
SPARKS, MARYLAND 21152
TELEPHONE: (410) 316-7800
FAX: (410) 316-7818

DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION PRINCE GEORGE'S COUNTY, MARYLAND		SCALE: 1"=10'		DWG. 3 OF 6	
PISCATAWAY DRIVE		APPROVED		FOR DARRELL B. MORLEY, DIRECTOR	
CROSS SECTIONS		DESIGNED: DKH		CONTRACT NO. XXX-XXX	
CS-3		DRAWN: BBB		ROAD NO. JOB NO.	
		CHECKED: KTB		FILE NO.	
		APPROVED:			
		CHEF, DIV. OF HIGHWAYS & BRIDGES		DATE	

Monday, May 19, 2014 AT 09:41 AM
M:\2010\07100627.W\Drawings\Roadway\pHC-X001_piscataway.dgn






KCI
TECHNOLOGIES

ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS

936 RIDGEBROOK ROAD
SPARKS, MARYLAND 21152
TELEPHONE: (410) 316-7800
FAX: (410) 316-7818

DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION PRINCE GEORGE'S COUNTY, MARYLAND		SCALE: 1"=10'		DWG. 4 OF 6	
		APPROVED _____ DATE _____		FOR DARRELL B. MORLEY, DIRECTOR	
PISCATAWAY DRIVE CROSS SECTIONS		DESIGNED: DKH	CONTRACT NO. XXX-XXX		
		DRAWN: BBB	ROAD NO. _____ JOB NO. _____		
		CHECKED: KTB	FILE NO. _____		
APPROVED: _____		CHEF, DIV. OF HIGHWAYS & BRIDGES			
CS-4		DATE _____			

Monday, May 19, 2014 AT 09:41 AM
M:\2010\07100627\Drawings\Roadway\pHC-X001_piscataway.dgn



ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS

936 RIDGEBROOK ROAD
SPARKS, MARYLAND 21152
TELEPHONE: (410) 316-7800
FAX: (410) 316-7818


DEPARTMENT OF PUBLIC WORKS
AND TRANSPORTATION
PRINCE GEORGE'S COUNTY, MARYLAND

PISCATAWAY DRIVE
CROSS SECTIONS

SCALE: 1"=10'		DWG. 5 OF 6	
APPROVED		FOR DARRELL B. MORLEY, DIRECTOR	
DESIGNED: DKH		CONTRACT NO. XXX-XXX	
DRAWN: BBB		ROAD NO.	JOB NO.
CHECKED: KTB		FILE NO.	
APPROVED:		DATE	
CHIEF, DIV. OF HIGHWAYS & BRIDGES			

PLOTTED: Monday, May 19, 2014 AT 09:41 AM
FILE: M:\2010\07100627\Drawings\Roadway\pHC-X001_piscataway.dgn

Monday, May 19, 2014 AT 09:42 AM
M:\2010\07100627.W\Drawings\Roadway\pHC-X001_plscataway.dgn



KCI TECHNOLOGIES
ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS
936 RIDGEBROOK ROAD
SPARKS, MARYLAND 21152
TELEPHONE: (410) 316-7800
FAX: (410) 316-7818

DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION PRINCE GEORGE'S COUNTY, MARYLAND		SCALE: 1"=10'		DWG. 6 OF 6	
PISCATAWAY DRIVE		APPROVED		FOR DARRELL B. MORLEY, DIRECTOR	
CROSS SECTIONS		DESIGNED: DKH		CONTRACT NO. XXX-XXX	
CS-6		DRAWN: BBB		ROAD NO. JOB NO.	
		CHECKED: KTB		FILE NO.	
		APPROVED:			
		CHIEF, DIV. OF HIGHWAYS & BRIDGES		DATE	

PLOTTED: Monday, May 19, 2014 AT 09:42 AM
FILE: M:\2010\07100627.W\Drawings\Roadway\pHC-X001_plscataway.dgn

ROADWAY PLANS

INDEX OF SHEETS

1	T-1	TITLE SHEET
2	AB-1	ABBREVIATIONS SHEET
3	TS-1	ROADWAY DETAIL&TYPICAL SECTION
4	GS-1	GEOMETRY SHEET
5-6	PS-1 TO PS-2	ROADWAY PLANS
7-8	PR-1 TO PR-2	ROADWAY PROFILES
1-6	CS-1 TO CS-6	ROADWAY CROSS SECTIONS

DEPARTMENT OF PUBLIC WORKS
AND TRANSPORTATION
PRINCE GEORGE'S COUNTY, MARYLAND


ROADWAY IMPROVEMENTS
TO

PISCATAWAY DRIVE

CONTRACT NO.

PROJECT NO. XXX-XXX-XX

F.A.P.NO. BRF - XXXX (X) X




LOCATED IN PRINCE GEORGES COUNTY

LENGTH OF PROJECT = X.XXX MILES

VICINITY MAP
SCALE: 1"=1000'

EROSION AND SEDIMENT CONTROL
REGULATIONS WILL BE STRICTLY ENFORCED
DURING CONSTRUCTION



Professional Certification. I hereby certify that these documents were prepared or approved by me, and that I am a duly licensed professional engineer under the laws of the State of Maryland,

License No., Expiration Date:

HORIZONTAL DATUM	NAD 83 /91
VERTICAL DATUM	NAVD 88



ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS

936 Ridgebrook Road
Sparks, Md 21152
Phone:(410) 316-7800
Fax:(410) 316-7817
www.kci.com

OWNER'S/DEVELOPER'S/APPLICANT INFORMATION

NAME:	PRINCE GEORGE'S COUNTY GOVERNMENT
ADDRESS:	DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION INGLEWOOD CENTER 3 9400 PEPPERCORN PLACE, SUITE 310 LARGO, MD 20774
REPRESENTATIVE:	EDWARD J. BINSEEL CHIEF, HIGHWAYS & BRIDGES
PHONE:	(301) 883-5642

UTILITY CERTIFICATION

I HEREBY CERTIFY THAT THE EXISTING AND/OR PROPOSED UNDERGROUND UTILITY INFORMATION SHOWN HEREON HAS BEEN CORRECTLY DUPLICATED FROM UTILITY COMPANY RECORDS. FURTHER, THAT THIS PROJECT HAS BEEN CAREFULLY COORDINATED WITH EACH INVOLVED UTILITY COMPANY AND ALL AVAILABLE UNDERGROUND UTILITY INFORMATION RELATIVE TO THE PLAN HAS BEEN SOLICITED FROM THEM.

SIGNATURE: DATE:

	INSPECTION BY DPW&T
<u>STORM DRAIN SYSTEM</u> S.D. PIPES S.D. FLOOD CONTROL <u>WATER QUALITY SYSTEM</u> INFILTRATION RETENTION POND BIORETENTION LOW IMPACT DEVELOPMENT EXT. DET. POND UNDERGROUND STORAGE GRASS SWALE W/ CHECK DAMS <u>OTHERS</u>	
SD * XXXXX - XXXX - XX	
PROJECT NAME	
PRINCE GEORGE'S COUNTY, MD. DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION, OFFICE OF ENGINEERING APPROVED for Stormwater Management and Storm Drain Only Date	
(✓)	Public stormdrain/SWM system permits required prior to construction
()	Private stormdrain/SWM system A recorded maintenance agreement is required
(✓)	Preconstruction meeting is required for all DPW&T inspected stormwater management/storm drain systems. Call (301) 952-4914 to arrange.

T - 1

DEPARTMENT OF PUBLIC WORKS
AND TRANSPORTATION
PRINCE GEORGE'S COUNTY, MARYLAND

PISCATAWAY DRIVE

TITLE SHEET

SCALE: AS SHOWN DWG. 1 OF 8

APPROVED	DATE	FOR Dam/B. Mody, DIRECTOR
DESIGNED: DKH	CONTRACT NO. xx-001	
DRAWN: BBB	ROAD NO.	JOB NO.
CHECKED: KTB	FILE NO.	
APPROVED:	DATE	CHIEF, HIGHWAYS AND BRIDGES

ABBREVIATIONS

A.A.S.H.T.O....American Association of State Highway Transportation Officials	IN.....Inch	R.Q.D.Rock Quality Designation
ADT.....Average Daily Traffic	I.S.T.....Inlet Sediment Trap	R.M.Rootmat
AHD.....Ahead	INV.....Invert	SSouth
APPROX.....Approximate	J.B.....Junction Box	SAN.Sanitary Sewer
B or BLBaseline	KK Inlet	SB or S/BSouthbound
BKBack /Book	LLength	S.D.Storm Drain
BIT.Bituminous	L.F.Linear Feet	S.D.D.Surface Drain Ditch
B.C.....Bituminous Concrete	L.L.Liquid Limit	SESuper Elevation
B.M.....Bench Mark	LPLow Point	SFSilt Fence
BOT.....Bottom	L.P.Light Pole	S.F.Square Feet
C.C.....Center of Curve	LT.....Left	SHT.Sheet
CATV.....Cable Television	MAC.....Macadam	S.P.P.Structural Plate Pipe
C.B.R.....California Bearing Ratio	M.C.....Moisture Content	S.P.T.Standard Penetration Testing
CL or CLCenterline	MAX.Maximum	SSDStopping Sight Distance
CLClass	M.D.D.....Maximum Dry Content	SSFSuper Silt Fence
CLF.....Chainlink Fence	MOD.....Modified	STD.Standard
CMP.....Corrugated Metal Pipe	MIN.....Minimum	STA.Station
C.O.....Cleanout	N.....North	SO.Single Opening
COMB.....Combination	N.B.....Northbound	S.Y.Square Yards
CONC.....Concrete	N.E.....Northeast	SWMStormwater Management
CONSTR.Construction	N.P.Non-Plastic	TTangent
COR.....Corner	O.C.On Center	TTelephone
CORR.....Correction	OHEOverhead Electric	T.C.Top of Cover
C.Y.....Cubic Yard	O.M.Optimum Moisture	T.G.Top of Grate
DCDegree of Curve	PAV.T.....Pavement	T or TLTraverse Line
D.H.V.....Design Hourly Volume	P.C.Point of Curvature	T.M.Top of Manhole
D.I.Drop Inlet	P.C.C.....Point of Compound Curvature	TRAV.Traverse
DIA.Diameter	P.C.Point of Crown	TSTemporary Swale
D.O.....Double Opening	PGEProfile Grade Elevation	T.S.Top of Slab
EEast	P.G.E.....Profile Ground Elevation	T.S.Topsoil
EElectric	P.G.L.....Profile Grade Line	TYP.Typical
EExternal Distance	PGLProfile Ground Line	U.D.Under Drain
EA.Each	P/RPoint of Rotation	U.G.Underground
E.B.....Eastbound	P.I.Plasticity Index	U.P.Utility Pole
ELEV.Elevation	P.I.Point of Intersection	U.S.D.A.....United States Department of Agriculture
E.R.C.C.P.Elliptical Reinforced Cement Concrete Pipe	P.O.B.....Point of Beginning	VCLVertical Clearance
ESEnd Section	P.O.C.....Point On Curve	V.C.L.....Vertical Curve Length
EX.or.EXIST.....Existing	P.O.E.....Point of End	WWater
FT.Feet	P.O.T.....Point On Tangent	WWest
F or FL.....Flowline	PROP.....Proposed	W.B.....Westbound
F.B.D.....Flat Bottom Ditch	P.R.C.....Point of Reverse Curve	WBWetland Buffer
F.H.Fire Hydrant	PT.Point	W.M.Water Meter
FWD.....Forward	P.T.Point of Tangency	W.S.Wrapped Steel
GGas	P.V.C.....Point of Vertical Curve	WUSWaters of the United States
G.V.Gas Valve	PVCPolyvinyl Chloride	W.V.Water Valve
H.B.Handbox	PVIPoint of Vertical Intersection	
H.D.P.....High Density Polyethylene	PVRQ.....Point of Vertical Reverse Curve	
HDWL.Headwall	PVTPoint of Vertical Tangency	
H.E.R.C.P.Horizontal Elliptical Reinforced Concrete Pipe	RRadius	
HPHigh Point	R.F.Rock Fragments	
	RT.Right	
	RW or RW.....Right of Way	
	R.C.P.Reinforced Cement Pipe	
	R.C.C.P.Reinforced Cement Concrete Pipe	

SOILS LEGEND

SOILS LEGEND

A-3
SAND

A-2
SAND & FINES

A-2-4
SILTY SAND

A-4-2
SANDY SILT

A-2-7
CLAYEY SAND

A-7-2
SANDY CLAY

A-4
SILT

A-4-7
CLAYEY SILT

A-7-4
SILTY CLAY

A-7
CLAY

A-6
COLLOIDAL CLAY

A-5
MICA, DIATOMS

PLAN LOCATION OF SOIL BORINGS

TS-TOPSOIL
RM-ROOT MAT
BC-BITUMINOUS CONCRETE
SB-STONE BASE
PCC-PORTLAND CEMENT CONCRETE
RPPSA - ROCK PENETRATED BY POWER SOIL AUGER

BORING TARGETS AND PROFILES SCALE:
HORIZONTAL - NONE
VERTICAL - SEE PROFILE SHEETS

LL-LIQUID LIMIT (%)
PI-PLASTICITY INDEX (%)
NP-NON-PLASTIC
MDD-MAXIMUM DRY DENSITY (pcf)
OMC-OPTIMUM MOISTURE CONTENT (%)
USC-UNIFIED SOIL CLASSIFICATION
USDA-UNITED STATES DEPARTMENT OF AGRICULTURE CLASSIFICATION

w/GR-WITH GRAVEL
w/RF-WITH ROCK FRAGMENTS

NOTES: SOIL SYMBOLS DENOTE MSMT CLASSIFICATIONS

ALL DIMENSIONS, DEPTHS AND ELEVATIONS ARE NOTED IN FEET

AN ASTERISK AT THE TOP DEPTH OF STRATA INDICATES THAT STRATA WAS VISUALLY CLASSIFIED BY DRILLER

MDD & OMC PER A.A.S.H.T.O. DESIGNATION T-180

N PER A.A.S.H.T.O. DESIGNATION T-206

UNLESS OTHERWISE NOTED ON PLANS, ALL SOIL SURVEY BORINGS FOR ROADWAY CONSTRUCTION WERE LEFT OPEN FOR 24 HOURS WITH NO EXCESS MOISTURE OR FREE WATER ENCOUNTERED DURING TIME OF SOIL SURVEY (SOIL AND SWM BORINGS IN SEPTEMBER 2012)

EXAMPLE SOIL BORING PROFILE

SOILS TEST DATA								
BORING NUMBER	SAMPLE DEPTH	LL	PI	USDA	USC	MDD	OMC	REMARKS
B-09	1.8 - 8.0	18	NP	SANDY LOAM	-	-	-	w/GR
B-09	8.0 - 14.0	41	22	SILTY CLAY LOAM	CL	121	12	-

CONVENTIONAL SIGNS (SAMPLES)

PROPOSED MEDIAN BARRIER		PROPOSED PIPE /CULVERT	
ELECTRICAL HAND BOX - SIGNALS		EXISTING PIPE /CULVERT	
FLOW LINE		EXISTING DROP INLET	
STATE, COUNTY OR CITY LINES		UTILITY POLE	
PROPOSED TRAFFIC BARRIER		WETLAND	
EXISTING TRAFFIC BARRIER		WETLAND BUFFER	
PROPOSED FENCE LINE		WATERS OF THE U.S.	
EXISTING FENCE LINE		HEDGE /TREE LINE	
RIGHT OF WAY LINE		BUSH /TREE	
EXISTING ROADWAY		CONIFEROUS TREE	
RAILROAD		GROUND ELEVATION	
BASE LINE OR SURVEY LINE		GRADE ELEVATION	
FIRE HYDRANT		HEDGE	
HISTORIC BOUNDARY		SILT FENCE	
WATERS OF THE U.S.		EARTH DIKE	
PROPERTY LINE		TRAFFIC BARRIER W/BEAM	
LEGEND BASELINE CONSTRUCTION		WARNING SIGNS	
EXISTING SEWER LINE		CHANNELIZING DRUMS	
DRY SWALE		WORK ZONE	
LIMIT OF DISTURBANCE		TREE PROTECTION	
FIBER OPTIC CABLE			
FILL			
WETLAND BOUNDARY			
WUS BOUNDARY			


ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS

936 RIDGEBROOK ROAD
SPARKS, MARYLAND 21152
TELEPHONE: (410) 316-7800
FAX: (410) 316-7818

REVISIONS		SCALE: N/A DWG. 2 OF 8	
APPROVED		DATE	
DESIGNED: DKH		FOR DARRELL B. MORLEY, DIRECTOR	
DRAWN: BBB		CONTRACT NO. XXX-XXX	
CHECKED: KTB		ROAD NO. JOB NO.	
APPROVED:		FILE NO.	
CHIEF, DIV. OF HIGHWAYS & BRIDGES		DATE	

Monday, May 19, 2014 AT 09:03 AM
\\corp.kci.com\sporks-projects\2010\07100627.M Drawings\Roadway\p0N-ND01_Abbrevs.dgn

Monday, May 19, 2014 AT 09:03 AM
\\corp.kci.com\sparks-projects\2010\07100627.W\Drawings\Roadway\pht-X000.piscataway.dgn



NOTE:
EXISTING BITUMINOUS CURB IS PRESENT IN SOME AREAS AND
A 4' SHOULDER FROM APPROXIMATELY STA. 21+50 TO 25+00.

PAVEMENT LEGEND

- | | | |
|---|------|---|
| ① | 1.5" | HOT-MIX ASPHALT SUPERPAVE 9.5mm FOR SURFACE, PG 64-22, LEVEL-2 |
| ② | 1.5" | HOT-MIX ASPHALT SUPERPAVE 9.5mm, PG 64-22, LEVEL-2 |
| ③ | 3.0" | HOT-MIX ASPHALT SUPERPAVE BASE, 19.0mm, PG 64-22, LEVEL-2 |
| ④ | 4.0" | GRADED AGGREGATE SUBBASE |
| ⑤ | | 6" LONGITUDINAL UNDERDRAIN (STD. 300.14, GEOTEXTILE FABRIC TO BE MSMT CLASS SD TYPE II OR APPROVED EQUAL) |

DEPARTMENT OF PUBLIC WORKS
AND TRANSPORTATION
PRINCE GEORGE'S COUNTY, MARYLAND

PISCATAWAY DRIVE

TS-1


TYPICAL SECTIONS

SCALE: N.T.S.		DWG. 3 OF 8	
APPROVED		DATE	FOR DARRELL B. MORLEY, DIRECTOR
DESIGNED: DKH	CONTRACT NO. XXX-XXX		
DRAWN: BBB			
CHECKED: KTB	ROAD NO. JOB NO.		
APPROVED:	FILE NO.		
CHEF, DIV. OF HIGHWAYS & BRIDGES	DATE		




ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS
936 RIDGEBROOK ROAD
SPARKS, MARYLAND 21152
TELEPHONE: (410) 316-7800
FAX: (410) 316-7818

Monday, May 19, 2014 AT 09:03 AM
\\corp.kci.com\sparks-projects\2010\07100627.M Drawings\Roadway\p05-P001_piscataway.dgn



LOCATION	CURVE	STATION	NORTH	EAST	BEARING
PISCATAWAY DRIVE	PISC-1	POT 20+00.00	376,006.4903	1,312,449.6269	N57°47'50.00"E
		PC 21+09.99	376,065.1084	1,312,542.7008	
		PI 21+72.95	376,098.6557	1,312,595.9673	
		PT 22+34.09	376,150.7849	1,312,631.2559	
	PISC-2	PC 26+95.88	376,533.1885	1,312,890.1222	N34°05'45.04"E
		PI 27+91.80	376,612.6244	1,312,943.8959	
		PT 28+81.56	376,646.1251	1,313,033.7813	
	PISC-3	PC 32+05.81	376,759.3651	1,313,337.6144	N69°33'33.60"E
		PI 32+63.02	376,779.3430	1,313,391.2167	
		PT 33+19.35	376,814.3937	1,313,436.4246	
	PISC-4	PC 33+19.35	376,814.3937	1,313,436.4246	N52°12'45.91"E
		PI 33+87.15	376,855.9361	1,313,490.0054	
		PT 34+53.27	376,914.5506	1,313,524.0790	
	PISC-5	PC 35+68.11	377,013.8360	1,313,581.7953	N30°10'12.67"E
		PI 36+91.12	377,120.1803	1,313,643.6151	
		PT 38+01.58	377,239.3126	1,313,612.9840	S76°19'25"E
		POT 38+76.35	377,311.7291	1,313,594.3644	

CURVE DATA						
CURVE	DELTA	Dc	RADIUS	TANGENT	LENGTH	EXTERNAL
PISC-1	23°42'04.96"	19°05'54.94"	300.0000'	62.9503'	124.1001'	6.5334
PISC-2	35°27'48.56"	19°05'54.94"	300.0000'	95.9254'	185.6864'	14.9630'
PISC-3	17°20'47.70"	14°41'28.41"	390.0000	115.0324'	223.7210'	16.6109'
PISC-4	22°02'33.23"	16°27'33.821"	348.1038'	57.2042'	113.5331'	4.3380'
PISC-5	44°35'22.67"	19°05'54.94"	300.0000'	123.0073'	233.4708'	24.2388'



ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS

936 RIDGEBROOK ROAD
SPARKS, MARYLAND 21152
TELEPHONE: (410) 316-7800
FAX: (410) 316-7818

REVISIONS

DEPARTMENT OF PUBLIC WORKS
AND TRANSPORTATION
PRINCE GEORGE'S COUNTY, MARYLAND

PISCATAWAY DRIVE

GS-1

GEOMETRIC LAYOUT SHEET

SCALE: 1" = 100' DWG. 4 OF 8



APPROVED

DESIGNED: DKH
DRAWN: BBB
CHECKED: KTB
APPROVED:

CONTRACT NO. XXX-XXX
ROAD NO. JOB NO.
FILE NO.

CHEF, DIV. OF HIGHWAYS & BRIDGES

Monday, May 19, 2014 AT 09:03 AM
\\corp.kci.com\sparks-projects\2010\07100627.W\Drawings\Roadway\p01-P01_Piscataway.dgn




LIMIT OF WORK
< CONTR. NO >
PISCATAWAY DRIVE
STA. 20+00.00

LEGEND

- FULL DEPTH
- MILL AND OVERLAY
- PROPOSED TRAFFIC FLOW

NOTE:
1. MULTIPLE LONGITUDINAL CRACKING OCCURS WITHIN THE PROJECT LIMITS.




ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS

936 RIDGEBROOK ROAD
SPARKS, MARYLAND 21152
TELEPHONE: (410) 316-7800
FAX: (410) 316-7818

REVISIONS

DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION PRINCE GEORGE'S COUNTY, MARYLAND	
PISCATAWAY DRIVE PS-1	
ROADWAY PLAN SHEETS	
SCALE: 1" = 30'	DWG. 5 OF 8
APPROVED _____ DATE _____ FOR DARRELL B. MORLEY, DIRECTOR	
DESIGNED: DKH	CONTRACT NO. XXX-XXX
DRAWN: BBB	ROAD NO. _____ JOB NO. _____
CHECKED: KTB	FILE NO. _____
APPROVED: _____	
CHEF, DIV. OF HIGHWAYS & BRIDGES	DATE _____

Monday, May 19, 2014 AT 09:03 AM
\\corp.kci.com\sparks-projects\2010\07100627.M Drawings\Roadway\p02-P002.piscataway.dgn



DEPARTMENT OF PUBLIC WORKS AND TRANSPORTATION PRINCE GEORGE'S COUNTY, MARYLAND			
PISCATAWAY DRIVE			PS-2
ROADWAY PLAN SHEETS			
SCALE: 1" = 30'		DWG. 6 OF 8	
APPROVED		DATE	FOR: DARRELL B. MOBLEY, DIRECTOR
DESIGNED: DKH		CONTRACT NO. XXX-XXX	
DRAWN: BBB		ROAD NO.	
CHECKED: KTB		JOB NO.	
APPROVED:		FILE NO.	
CHEF, DIV. OF HIGHWAYS & BRIDGES		DATE	




KCI
TECHNOLOGIES

ENGINEERS
PLANNERS
SCIENTISTS
CONSTRUCTION MANAGERS

936 RIDGEBROOK ROAD
SPARKS, MARYLAND 21152
TELEPHONE: (410) 316-7800
FAX: (410) 316-7818

REVISIONS	

Monday, May 19, 2014 AT 09:03 AM
\\corp.kci.com\sparks-projects\2010\07100627.W\Drawings\Roadway\pdp-V001_Piscataway.dgn




PISCATAWAY DRIVE PROFILE GRADE LINE

HORIZONTAL SCALE: 1" = 30'
VERTICAL SCALE: 1" = 5'



REVISIONS		SCALE: AS SHOWN		DWG. 7 OF 8	
APPROVED		DATE		FOR DARRELL B. MORLEY, DIRECTOR	
DESIGNED: DKH		DRAWN: BBB		CONTRACT NO. XXX-XXX	
CHECKED: KTB		APPROVED:		ROAD NO.	JOB NO.
CHEF, DIV. OF HIGHWAYS & BRIDGES		DATE		FILE NO.	

Monday, May 19, 2014 AT 09:03 AM
\\corp\kci.com\sparks-projects\2010\07100627.M Drawings\Roadway\pHP-V002.piscataway.dgn



PISCATAWAY DRIVE PROFILE GRADE LINE

HORIZONTAL SCALE: 1" = 30'
VERTICAL SCALE: 1" = 5'



REVISIONS		SCALE: AS SHOWN		DWG. 8 OF 8	
APPROVED		DATE		FOR DARRELL B. MORLEY, DIRECTOR	
DESIGNED: DKH		DRAWN: BBB		CONTRACT NO. XXX-XXX	
CHECKED: KTB		APPROVED:		ROAD NO.	JOB NO.
CHEF, DIV. OF HIGHWAYS & BRIDGES		DATE		FILE NO.	

DEPARTMENT OF PUBLIC WORKS
AND TRANSPORTATION
PRINCE GEORGE'S COUNTY, MARYLAND

PISCATAWAY DRIVE

PR-2

ROADWAY PROFILE